Summary of Tritium Detected in Groundwater Monitoring Wells\* Pilgrim Nuclear Power Station, Plymouth, MA- All Results Reported in picocuries per liter (pCi/L)

Sample Collection Date	Reported By	Tritium Concentration (pCi/L)																	
		MW-201	MW-202	MW-202I**	MW-203	MW-204	MW-205**	MW-206**	MW-207**	MW-208S**	MW-208I**	MW-209**	MW-210**	MW-211**	MW-212**	MW-213**	MW-214**	MW-3	MW4
November 29, 2007	Entergy	3,192	451		NDA<447	1,366												N.S.	N.S.
	Entergy	3,300	525		N.A.	1,586												N.S.	N.S.
	Entergy		733															N.S.	N.S.
	MDPH/MERL	3,014	522		371	1,277											I F	N.S.	N.S.

Notes: \* Entergy samples collected and analyzed by Entergy contract laboratory; MDPH split samples received from Entergy and analyzed by MDPH/RCP Massachusetts Environmental Radiation Laboratory (MERL) \*\*Groundwater Monitoring Wells MW-202I, MW-205, MW-206, MW-207, MW-208S, and MW-208I were installed in Spring 2010; Groundwater Monitoring Wells MW-209, MW-210, MW-211, MW-212, MW-213, and MW-214 were installed Summer 2010. \*\*\* Results pending

NDA< = Not detected at less than activity value listed N.A. = Not analyzed

N.S. = Not sampled