

Floor	Room #	Description	Replacement Date
Ground	G01	1 - Stained	
Ground	G01	2 - Stained (Outside of room)	
Ground	G02	Numerous missing, discolored & falling tiles	
Ground	G03	1 Stained & 1 Broken (Outside of room)	
Ground	G27	3 - Stained (outside of room)	
Ground	G32	1 - Stained (Outside of mens by double door)	
1st	110B	1- Broken tile by entrance	
1st	121A	Bathroom - No ceiling	
1st	121	Stain	
1st	121B	Missing tile, left side by window	
1st	114A	(DA) entering back hall, missing tiles	
1st	138	Outside in Hallway hole in tile	
1st	138B	(Bar Assoc.) Discolored and broken tiles	
1st		Outside of Court Services - Falling tile	
1st	171	Mens room missing tile	
1st	124	Lock-up stained missing & dirty tiles	
1st	130	Outside in hallway broken & stained tiles	
1st	139A	Falling & Stained tiles	
1st	139A	Bathroom Falling & Stained	
1st	139	Dirty Tiles	
1st	140	Far left by window, falling tile	
1st	140	Outside of room broken tile	
1st	144A	Employee Entrance, Security - Dirty Tiles	
1st		Hallway from Employee Entrance to Probation - Falling tiles	
1st	168	Lounge - 2 stained by Xerox machine	
1st	162	Broken tile	
1st	155	Miscolored tiles	
1st		Hallway outside of Room #141 & #142 - dirty tiles with encapsulated paint	
1st	147	Dirty tiles with encapsulated paint	
1st	148	Dirty tiles	
1st	149	Dirty tiles	
		Over by the rolling filing cabinets - stained & broken tiles	
2nd		Dist Court Rm #11 - 3 misaligned & Stained tiles	

2nd		Outside Dist. Court room #3 - Falling and Stained	
2nd		Hallway to Stairwell #3 - stained tiles	
2nd	251	Entrance to Conference Room #251 - Stained tile	
2nd	206	Right side close to rear, stained tile	
2nd	207B	Left side, stained tile	
2nd	208	Outside of room #208 - 2 broken tiles	
2nd	210A	Broken tiles	
2nd		Outside of stairwell #2 - broken tile	
2nd		In hallway between Dist. Court rooms 5 & 6 - Chipped and dirty tiles	
2nd	211	Falling Tiles	
2nd	213	Rear Entrance to Dist. Court Civil by room 213 - Chipped tiles	
2nd		Dist Court Civil front entrance to left	
2nd	265	Falling Tiles	
2nd		Outside Elevator #1 - misaligned tile	
2nd	263	Mens Public - too many to list, replace ceiling	
2nd	265 - 227	Aisle way from #265 Witness Advocate to #227 - bowed and chipped tiles	
2nd	225	Dirty and Falling tiles	
2nd	226	5 - Stained tiles	
2nd	222	Dirty and Falling tiles	
2nd	220	Dirty Tiles	
2nd	218	Outside of room, Chipped Tile	
2nd	222	Outside of room - Falling Tile	
2nd	230	Lock-up Outside of Cell #2, stained tile	
		Hallway from Stairwell #4 to #1 - Numerous tiles - stained, misaligned, falling or have holes	
2nd	242	to the left, there are 2 falling tiles. To the left there are 6 chipped and stained tiles	
2nd	241A	In corner 2 falling tiles	
2nd	244	Falling Tile	
2nd	246A	1 - Stained Tile	
2nd	246A	Bathroom - 2 stained tiles	
2nd	246	3 - Falling, chipped and stained tiles	
2nd	248	3- Stained Tiles	
2nd	249A	6 - Stained, chipped and falling tiles	
2nd	249	Numerous stained and miscolored tiles	
2nd	251A	3 - Chipped Tiles	

2nd	252	2 - Stained, 2 chipped, 1 falling tile	
3rd	301 & 302	Laura Gentile's office	
3rd	303	Dirty tiles	
3rd		Front Superior Court Criminal - numerous discolored and capsulated ceiling tiles	
3rd	309	Stained tile	
3rd	310	Missing tile	
3rd		Front of Library by windows to Plaza - numerous stained tiles not fitting correctly	
3rd	313	Jury Room left bathroom, tile falling	
3rd	315	Numerous stains and encapsulated paint tiles	
3rd	317	Stained ceiling tile	
3rd	317B	stained tile in corner by window	
3rd	319	Outside 319, missing tile	
3rd	320A	3 - stained tiles by window	
3rd	320B	1 - stained tile by window	
3rd		Outside, side entrance Superior Court Court Room #1 - missing tile	
3rd	389	Staff womens room, missing & broken tiles	
3rd		Attorneys Lounge - 10 missing tiles	
3rd	323	Lock-up - Falling down and missing tiles	
3rd		Superior Court Court Room #2, Conference A - 2 missing tiles	
3rd	380	Superior Court Probation - stain in middle	
3rd	344	Stain	
3rd		Outside of 350B (inside of probation) - stain	
3rd		Outside of stairwell #1 - Falling tile in between all the doors	
3rd	378	Grand Jury Room - stained, missing and falling tiles	
3rd	350A	Waiting room - few falling tiles	
3rd	350	Missing and stained tiles	
3rd	358	Missing tiles	
3rd	371	DA's Lounge - stained tiles, falling tiles	
3rd	371B	Mens Room in lounge - stained	
3rd	360	Holes in tile	
3rd	363	Broken tiles	
3rd	372A	Stained tiles	
3rd	373	stained tiles	
3rd	372B	Outside of room - missing tiles	

3rd	370	Conference room - stained and broken tiles	
3rd		By the back entrance to the DA's office and behind S.C. Court room #5 - missing tiles	
4th		Outside of Stairwell #2 - broken tile	6/3/2022
4th	416A	Stained tile	6/2/2022
4th	416B	Bathroom - stain & hole	6/2/2022
4th	422	Outside of room - stained tile	6/2/2022
4th	426	Leading to Probate Court Room #1 - stained	
4th	427B	Mens - missing tile	6/3/2022
4th	427C	Womens - All tiles discolored and 1 broken	
4th	426	Entrance - Stained tile	6/6/2022
4th	427	Lounge - 1 stained by sink	6/6/2022
4th	452	Outside of Mens room - 2 stained and 1 falling	6/6/2022
4th		Through double doors leading to Registry of Deeds - stained	6/6/2022
4th		Through double doors leading to Registry of Probate - 1 stained	6/6/2022
4th		Inside of Probate to the right - falling tile	6/7/2022
4th		To the left of stairwell #4 - 6 stained tiles	6/7/2022
4th		To the right of stairwell #4 - 4 stained tiles	
4th		Along the wall by cubicles - 4 broken tiles	
4th	431	Heading toward 431 in middle - 4 stained and falling tiles	
4th	444	2 stained tiles	
4th	441	tiles are discolored	
4th	443	tiles are discolored	
4th		Jury Pool - inside the entrance to left, 6 encapsulated painted tiles	
4th		Jury Pool -8 or 9 stained and falling tiles	
4th		Inside Jury Pool by vending machines - 3 stained to the left, 3 in front of vending machines	
		stained, numerous stains to the right by womens room	
4th		Inside Probate Probation - numerous broken, discolored & falling tiles	
4th		Outside entrance of Registry of Deeds - 2 broken tiles	
4th		Right Inside entrance of Registry of Deeds - 1 falling	
4th	407	3 - Falling	
4th	406	6 - Stained and missing tiles	
4th	407	1 - Broken	
4th	405	Outside of Mechanical room #405 - falling tiles	
4th		Right rear of room by dehumidifier - 2 stained and falling tiles	

		to the left of those - missing tile	
4th	401	Falling tile	
4th	403	Entrance - stained	
4th	403	Other end of #403 - broken and stained tiles	
4th	450	Missing and chipped tiles	
4th	413	Missing tile	
4th	415	Missing tile	
4th	415	Outside of room #415 - Falling and stained tiles	
4th	411	3 - discolored and holes	
4th	410	3 - Falling	
4th		Outside of Room #410 - 6 need replacing	
4th	408	8 - Missing and stained	

Areas that were inaccessible, therefore couldn't be checked

Floor	Room #	Description	Replacement Date
Ground	G03		
Ground	G37 - Carpentry		
Ground	G40C - Ground Level storage area for Superior Court Civil & Criminal		
2nd	202 District Court Criminal Supply room (Trisha Santamaria)		
3rd	301 & 302 - Superior Court Criminal & Civil		