

CHARLES D. BAKER Governor

KARYN E. POLITO Lieutenant Governor The Commonwealth of Massachusetts Executive Office of Health and Human Services Department of Public Health Bureau of Environmental Health Community Sanitation Program 180 Beaman Street, West Boylston, MA 01583 Phone: 508-792-7880 Fax: 508-792-7706 TTY: 508-835-9796

MARYLOU SUDDERS Secretary

EILEEN M. SULLIVAN Acting Commissioner

Tel: 617-624-6000 www.mass.gov/dph

February 3, 2015

Michael J. Ashe, Jr., Sheriff Hampden County Sheriff's Department 626 Randall Road Ludlow, MA 01056

Re: Facility Inspection - Western Mass Correctional Alcohol Center, Springfield

Dear Sheriff Ashe:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Western Mass Correctional Alcohol Center on January 21, 2015 accompanied by Dan Moran, Standards and Training Coordinator, and Paul Halfmann, Community Sanitation Program. Violations noted during the inspection are listed below including 5 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

BASEMENT

Buffer Room	
	No Violations Noted
Food Storage	
FC 4-903.11(B)(1)*	Protection of Clean Items, Storing: Styrofoam plates not stored in the inverted position
FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gasket dirty
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, freezer floor was dirty
Chemical Storage	
	No Violations Noted
Weight Room	
105 CMR 451.353*	Interior Maintenance: Arm curl machine padding damaged
105 CMR 451.353	Interior Maintenance: Light shield missing

Male Bathroom (#009)	
	No Violations Noted
Male Bathroom (#023) 105 CMR 451.126* 105 CMR 451.123 105 CMR 451.117	Hot Water: Hot water temperature recorded at 96 ⁰ F Maintenance: Ceiling vent dusty Toilet Fixtures: Toilet fixtures dirty
Female Bathroom (#021)	No Violations Noted
Female Bathroom (#110) 105 CMR 451.123	Maintenance: Light shield broken
Records	No Violations Noted
Laundry 105 CMR 451.353	Interior Maintenance: Dryer # 1 not working
Staff Dining	No Violations Noted
Library	No Violations Noted
Urinalysis Room 105 CMR 451.353	Interior Maintenance: Unlabeled chemical bottle
Barber Shop 105 CMR 451.353	Interior Maintenance: Hair clippers dirty
Tool Crib FC 4-602.12(B)	Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty
Property Room	Unable to Inspect – No Access
FIRST FLOOR	
Lobby	No Violations Noted
Kitchen FC 3-501.16(A)	Limitation of Growth of Organisms, Temperature and Time Control: Potentially hazardous food not held at the proper hot holding temperature, mashed potatoes held at
FC 3-302.12 FC 3-304.12(A)	 130°F Preventing Food and Ingredient Contamination: Unlabeled flour container Preventing Contamination from Utensils: Service utensils handle stored below the food
FC 3-304.12(A)	and container line, flour scoop in container Preventing Contamination from Utensils: Service utensils handle stored below the food and container line, chicken flavoring scoop in container
FC 6-501.12(A)	Maintenance and Operation; Cleaning: Facility not cleaned properly, cooler # 1 floor
FC 4-903.11(A)(3)	dirty Protection of Clean Items, Storing: Milk crate not stored 6" off the floor in cooler # 2

Dumpster	
FC 5-501.15(A) FC 5-501.110	Refuse, Recyclables, and Returnables; Facilities on Premises: Lid missing from dumpster Refuse, Recyclables, and Returnables; Operations and Maintenance: Refuse storage not inaccessible to vermin, trash bags outside of dumpster
Dining Room	No Violations Noted
Men's Bathroom 105 CMR 451.123	Maintenance: Soap dispenser broken
WOMEN'S UNIT 5	
Cells 105 CMR 451.353 105 CMR 451.353	Interior Maintenance: Ceiling vent rusted in cell # 146 Interior Maintenance: Ceiling vent damaged in cell # 148
Bathroom 105 CMR 451.126	Hot Water: Hot water temperature recorded at 98°F
Laundry/Janitor's Closet	No Violations Noted
Medical	No Violations Noted
Common Area FC 4-204.112(A)	Design and Construction, Functionality: Thermometer not functioning properly in refrigerator
SECOND FLOOR	
<u>UNIT 1</u>	
Day Room	No Violations Noted
Hallway	No Violations Noted
Bathroom	No Violations Noted
Cells 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353 105 CMR 451.350 105 CMR 451.141	Interior Maintenance: Ceiling paint damaged in cell # 202, 204, 206, and 208 Interior Maintenance: Ceiling vent rusted in cell # 202, 204, 206, and 208 Interior Maintenance: Window sill paint damaged in cell # 204, 206, and 208 Interior Maintenance: Wall paint damaged in cell # 204 Interior Maintenance: Window shade damaged in cell # 241 and 243 Structural Maintenance: Hole in wall in cell # 241 and 243 Screens: Screen damaged in cell # 256
Day Room (#216)	No Violations Noted

Day	Room	(#220)

No Violations Noted

machine dirty

<u>UNIT #2</u>

Day Room #1A 105 CMR 451.353

Interior Maintenance: Wall paint damaged

Interior Maintenance: Wall paint damaged Interior Maintenance: Chair seat damaged

Interior Maintenance: Baseboard damaged

Interior Maintenance: Ceiling panels damaged

Interior Maintenance: Ceiling panels damaged

Interior Maintenance: Couch cushion damaged

Interior Maintenance: Ceiling panels damaged

Interior Maintenance: Wet mop stored in sink Interior Maintenance: Floor tiles damaged

Interior Maintenance: Light shield missing

state of good repair, refrigerator gasket dirty

Structural Maintenance: Hole in wall

refrigerator dirty

Maintenance: Ceiling panels damaged

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty Maintenance and Operation, Equipment: Equipment components not maintained in a

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, interior of

Interior Maintenance: Caulking around water fountain damaged

Day Room # 1B FC 4-601.11(A)

PC 4-001.11(A)

105 CMR 451.353 FC 4-602.12(B) 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353

Day Room #2

105 CMR 451.353 105 CMR 451.353

Day Room #2A

105 CMR 451.353 105 CMR 451.353

Staff Bathroom

105 CMR 451.123

Janitor's Closet

105 CMR 451.353 105 CMR 451.353 105 CMR 451.353 105 CMR 451.353

CO's Office

FC 4-602.12(B) FC 4-501.11(B)

FC 4-601.11(A)

Bathroom

105 CMR 451.123

Cells

105 CMR 451.350Structural Maintenance: Window broken in cell # 241 and 254105 CMR 451.353Interior Maintenance: Wall paint damaged in cell # 236 and 246105 CMR 451.353Interior Maintenance: Ceiling panels damaged in cell # 231, 233, 234, 238, 240, and 244105 CMR 451.353Interior Maintenance: Ceiling vent rusted in cell # 230 and 234

Maintenance: Wall paint damaged in shower # 1 and 3

THIRD FLOOR

<u>UNIT #3</u>

Day Room	
105 CMR 451.353	Interior Maintenance: Baseboard dirty
FC 4-602.12(B)	Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty
FC 4-601.11(A)	Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee
	machine rusted
105 CMR 451.353	Interior Maintenance: Wall dirty
Day Room (#318)	
105 CMR 451.353	Interior Maintenance: Ceiling panel damaged
105 CMR 451.353	Interior Maintenance: Window sill paint damaged
Day Room (#322)	
105 CMR 451.353	Interior Maintenance: Ceiling panel damaged
	showed assumed coming pollor duringed
Library	
105 CMR 451.353	Interior Maintenance: Ceiling vent rusty
Janitor's Closet	
105 CMR 451.353	Interior Maintenance: Tile broken on wall
105 CMR 451.353	Interior Maintenance: Light shield missing
CO's Office	
105 CMR 451.353	Interior Maintenance: Unlabeled chemical bottle
Janitor's Closet in Bathroom	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, backflow preventer was leaking
105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket
105 CMR 451.353	Interior Maintenance: Water left in mop bucket
Bathroom	
105 CMR 451.123	Maintenance: Floor dirty in shower # 1 and 2
105 CMR 451.123	Maintenance: Floor generally dirty
105 CMR 451.123	Maintenance: Wall paint damaged in shower # 1 and 2
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1-6
105 CMR 451.123	Maintenance: Floor tiles damaged in shower # 5 and 6
105 CMR 451.123	Maintenance: Bench rusted in handicap shower
105 CMR 451.123	Maintenance: Toilet # 1 dirty
105 CMR 451.123	Maintenance: Handicap toilet was not working
105 CMR 451.123	Maintenance: Door paint peeling
C _11_	
Cells	Later Maintenant Mart and 11 / 200 204 200 226 244 246 1200
105 CMR 451.353	Interior Maintenance: Vent rusted in cell # 302, 304, 308, 336, 344, 346, and 388
105 CMR 451.353	Interior Maintenance: Ceiling panels damaged in cell # 302, 304, 308, 331, 332, 338, 340, 342, 344, and 346
105 CMR 451.350	Structural Maintenance: Hole in wall in cell # 308, 331, 340, 342, 344, and 346
105 CMR 451.353	Interior Maintenance: Window sill paint damaged in cell # 302, 304, 310, 344, and 346
105 CMR 451.353	Interior Maintenance: Window shade damaged in cell # 331
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, ceiling ventilation grille blocked in cell $#$ 310
Staff Bathroom (# 321)	
STATE DEGREEOUTE (II DEL)	

No Violations Noted

.

Janitor's Closet	
105 CMR 451.353	Interior Maintenance: Wall tiles damaged
105 CMR 451.353	Interior Maintenance: Light shield missing
105 CMR 451.353	Interior Maintenance: Ceiling panel missing
105 CMR 451.353	Interior Maintenance: Wet mop stored in sink

FOUNDATION HOUSE

Community Room	
105 CMR 451.353	Interior Maintenance: Wall paint damaged
Cells	
105 CMR 451.141	Screens: Screen damaged in cell # 354
105 CMR 451.350	Structural Maintenance: Wall damaged in cell # 339 and 364
105 CMR 451.353	Interior Maintenance: Window sill paint damaged in cell # 362
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, ceiling ventilation grille blocked in cell # 364
105 CMR 451.353	Interior Maintenance: Window shade damaged in cell # 341
Bathroom	
105 CMR 451.123	Maintenance: Soap scum on walls and floors in shower # 1-4
105 CMR 451.123	Maintenance: Floor generally dirty
Janitor's Closet in Bathroom	
105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
KITCHEN	
FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator # 1 gasket damaged
FC 4-204.112(A)	Design and Construction, Functionality: No functioning thermometer in refrigerator # 1 and 2
FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator # 2 gasket moldy
LAUNDRY	
105 CMR 451.353*	Interior Maintenance: Wet mop stored in bucket
105 CMR 451.353	Interior Maintenance: Light shield missing
105 CMR 451.353	Interior Maintenance: Debris behind dryer

Observations and Recommendations

1. The inmate population was 151 at the time of inspection.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at <u>www.mass.gov/dph/dcs</u> and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X – Minimum Sanitation Standards for Food Establishments" and "<u>1999 Food Code</u>".

To review the Labeling regulations please visit the Food Protection website at <u>www.mass.gov/dph/fpp</u> and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,

herry Wagne

Kerry Wagner Environmental Health Inspector, CSP, BEH

Suzanne K. Condon, Associate Commissioner, Director, BEH
Steven Hughes, Director, CSP, BEH
Jay Youmans, Director of Government Affairs
Marylou Sudders, Secretary, Executive Office of Health and Human Services
Carol Higgins O'Brien, Commissioner, DOC
James Kelleher, Assistant Superintendent
Corporal Steve Sabol, EHSO
Helen R. Caulton Harris, H&HS, Director, Springfield Health Department
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Andrea Cabral, Secretary, EOPS

cc: