



DEVAL L. PATRICK  
GOVERNOR

TIMOTHY P. MURRAY  
LIEUTENANT GOVERNOR

JUDYANN BIGBY, MD  
SECRETARY

JOHN AUERBACH  
COMMISSIONER

# The Commonwealth of Massachusetts

Executive Office of Health and Human Services

Department of Public Health

Bureau of Environmental Health

Community Sanitation Program

180 Beaman Street

West Boylston, MA 01583

Telephone: 508-792-7880, ext. 2322

Facsimile: 508-792-7706

TTY: 508-835-9796

Amy.M.Riordan@state.ma.us

April 27, 2012

Lewis Evangelidis, Sheriff  
Worcester County House of Corrections and Jail  
5 Paul X. Tivnan Drive  
West Boylston, MA 01583

Re: Facility Inspection

Dear Sheriff Evangelidis:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, and Department of Public Health Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Worcester County House of Corrections and Jail on April 10, 11 and 12, 2012 accompanied by Dennis Doyle, FSO, Michael O'Connor, FSO and Gene Desrosiers, Chemical Officer. Violations noted are listed below (*\* indicates conditions documented on previous inspection reports*).

## ENTRANCE

### *Hallway*

105 CMR 451.350\*                      Structural Maintenance: Door not rodent and weathertight

### *Male Locker Room*

105 CMR 451.350                      Structural Maintenance: Ceiling tile water stained

### *Fisher Conference Room*

No Violations Noted

### *Control Room*

FC 4-602.12(B)\*                      Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty  
FC 4-601.11(C)\*                      Cleaning of Equipment and Utensils, Objective: Non-food contact surface dirty,  
gaskets

105 CMR 451.353                      Interior Maintenance: Ceiling vent dusty in bathroom

105 CMR 451.123                      Maintenance: Paint peeling behind toilet in bathroom

### *Waiting Area*

No Violations Noted

## **HERMAN BUILDING**

105 CMR 451.320\*  
105 CMR 451.343\*

Cell Size: Inadequate floor space in cells  
Electric Fixtures in Cell: No electrical outlet in cells

### **A2 Block**

#### *Booth*

No Violations Noted

#### *Cells*

No Violations Noted

#### *Showers - Upstairs*

105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Tiles damaged  
Maintenance: Shower walls peeling paint  
Maintenance: Floor damaged  
Maintenance: Soap scum on walls in showers  
Maintenance: Baseboard damaged  
Maintenance: Missing floor drain  
Maintenance: Vent dusty

#### *Utility Closet - Upstairs*

105 CMR 451.123

Maintenance: Missing sink drain cover

#### *Showers - Downstairs*

105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Tiles damaged  
Maintenance: Shower floors peeling paint  
Maintenance: Floor damaged  
Maintenance: Soap scum on walls in showers  
Maintenance: Baseboard damaged  
Maintenance: Vents dusty in all showers

#### *Slop Sink - Downstairs*

105 CMR 451.130  
105 CMR 451.123

Plumbing: Plumbing not maintained in good repair, sink leaking  
Maintenance: Missing sink drain cover

#### *Office*

FC 4-602.12(B)\*  
FC 4-102.11(B)(2)\*  
FC 3-305.11(A)(3)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty  
Materials for Construction and Repair; Multiuse: Unused single-service article not protected against contamination  
Preventing Contamination from Premises: Food product stored in an inappropriate location, food product stored less than 6 inches from the floor

#### *Chemical Storage*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

#### *Paper Good Storage*

No Violations Noted

### **A1 Block**

#### *Booth*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty in bathroom

FC 4-204.112(A) Design and Construction, Functionality: No functioning thermometer in refrigerator, thermometer broken

*Cells (Up)*

105 CMR 451.103\* Mattresses: No mattress in cells

*Shower Upstairs*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, showers leaking

105 CMR 451.123 Maintenance: Face plate missing on both showers

*Slop Sink - Upstairs*

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, sink leaking

*Cells (Down)*

105 CMR 451.103 Mattresses: Mattress damage in cell #23

105 CMR 451.350 Structural Maintenance: Missing electrical plate in cell #21, 22 and 25-28

*Shower - Downstairs*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers

*Slop Sink Downstairs*

105 CMR 451.353\* Interior Maintenance: Ceiling vent dusty

105 CMR 451.123 Maintenance: Sink drain cover missing

*Storage #4*

No Violations Noted

*Storage #5*

No Violations Noted

**MAXI B**

105 CMR 451.320\* Cell Size: Inadequate floor space in cells

*Booth*

FC 4-602.12(B)\* Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

FC 4-903.11(A)(2)\* Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

105 CMR 451.110(B) Hygiene Supplies at Toilet and Handwash Sink: No waste receptacle at handwash sink

**Lower Right Tier**

*Day Room*

No Violations Noted

*Slop Sink*

No Violations Noted

*Showers*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers

105 CMR 451.123\* Maintenance: Tiles cracked

105 CMR 451.123 Maintenance: Missing dial plates in showers

*Cells*

No Violations Noted

**Lower Left Tier**

*Day Room*

No Violations Noted

*Cells*

No Violations Noted

*Lower Disciplinary Unit*

Not In Use

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

**Upper Left Tier**

*Day Room*

FC 4-602.12(B)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

*Cells*

No Violations Noted

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

105 CMR 451.123

Maintenance: Missing dial plate in showers

*Upper Disciplinary Unit*

No Violations Noted

**Upper Right Tier**

*Day Room*

No Violations Noted

*Cells*

No Violations Noted

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

105 CMR 451.123

Maintenance: Tile damaged

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, 1 shower leaking

**CHAPEL**

No Violations Noted

**HEALTH SERVICES**

*Infirmity Ward*

Not Occupied

*Staff Bathroom*

105 CMR 451.123

Maintenance: Ceiling vent dusty

105 CMR 451.123	Maintenance: Ceiling tile damaged
<i>Inmate Bathroom</i>	
105 CMR 451.123	Maintenance: Ceiling vent dusty
<i>Supply Closet</i>	
	No Violations Noted
<i>Property</i>	
	No Violations Noted
<i>Mental Health Offices</i>	
FC 4-602.12(B)	Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty
<i>Storage Room with Sink</i>	
	No Violations Noted
<i>Storage Room w/o Sink</i>	
	No Violations Noted
<i>Nurse's Room</i>	
	No Violations Noted
<i>Segregation Cells</i>	
	No Violations Noted
<i>Biohazard Storage</i>	
	No Violations Noted
<i>Pharmacy</i>	
105 CMR 451.350	Structural Maintenance: Green cabinet damaged
105 CMR 451.350*	Structural Maintenance: Ceiling tiles water stained

### **CENTRAL CONTROL**

105 CMR 451.350	Structural Maintenance: Wall damaged in control area above electrical panel
105 CMR 451.350*	Structural Maintenance: Wall damaged in bathroom
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty in bathroom
105 CMR 451.353*	Interior Maintenance: Mop stored in bucket
FC 4-501.11(B)*	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets are dirty
FC 4-903.11(A)(2)*	Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

### **VISITING ROOM**

105 CMR 451.350*	Structural Maintenance: Ceiling damaged at skylights on both inmate and visitor sides
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, bubbler not working
<i>Female Handicapped Bathroom</i>	
105 CMR 451.123	Maintenance: Ceiling vent dusty
<i>Female Bathroom</i>	
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, hot water not working
105 CMR 451.123	Maintenance: Ceiling tiles damaged

*Male Handicapped Bathroom*

105 CMR 451.110(A) Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink

*Male Bathroom*

105 CMR 451.123\* Maintenance: Ceiling tiles water stained  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, cold water not working

**GYMNASIUM**

105 CMR 451.350\* Structural Maintenance: Floor is bubbling, creating a tripping hazard  
105 CMR 451.350 Structural Maintenance: Door not rodent and weathertight

*Mini Side Bathroom*

105 CMR 451.123 Maintenance: Generally dirty  
105 CMR 451.123 Maintenance: Wall damaged  
105 CMR 451.110(A) Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink  
105 CMR 451.110(A) Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

*Maxi Side Bathroom*

105 CMR 451.110(A) Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink  
105 CMR 451.110(A) Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

*Booth*

105 CMR 451.123 Maintenance: Ceiling vent dusty in bathroom  
105 CMR 451.123 Maintenance: Missing sink drain cover  
105 CMR 451.353 Interior Maintenance: Mop stored in bucket

**MAXI C**

105 CMR 451.320\* Cell Size: Inadequate floor space in cells

*Booth*

FC 4-903.11(A)(2)\* Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination  
FC 4-602.12(B) Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty  
105 CMR 451.353 Interior Maintenance: Ceiling vent dusty in bathroom

**Upper Tier**

*Day Room*

No Violations Noted

*Cells*

105 CMR 451.102 Pillows and Linens: Linens damaged in cell #422  
105 CMR 451.350 Structural Maintenance: Missing face plate on electrical outlets in all cells  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, toilet leaks in cell #425

*Showers*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers  
105 CMR 451.123 Maintenance: Tile damage in showers  
105 CMR 451.123 Maintenance: Missing face plate on shower #3

*Old Segregation*

Not In Use

*Slop Sink*

105 CMR 451.353

Interior Maintenance: Mop stored in bucket

**Lower Tier**

105 CMR 451.350\*

Structural Maintenance: Door in rear hall not rodent and weathertight

*Cells*

105 CMR 451.350

Structural Maintenance: Missing face plate on electrical outlets in all cells

105 CMR 451.350

Structural Maintenance: Wall damage in cell #247

*Showers*

105 CMR 451.123\*

Maintenance: Missing face plate on dial in shower

105 CMR 451.123

Maintenance: Soap scum on walls in showers

*Segregation*

Not In Use

*Chemical Area*

No Violations Noted

*Day Room*

No Violations Noted

**DEIGNAN BUILDING**

105 CMR 451.320\*

Cell Size: Inadequate floor space in cells

*Officer's Booth*

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, gaskets damaged on refrigerator

**Upper West**

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

*Slop Sink Room*

No Violations Noted

*Bathroom*

Unable to Inspect – In Use

**Lower West**

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

105 CMR 451.123\*

Maintenance: Ceiling vent dusty

105 CMR 451.123\*

Maintenance: Appearance of mold like substance on floors and walls

105 CMR 451.123

Maintenance: Missing wall tiles under bench in showers

*Bathroom*

105 CMR 451.123

Maintenance: Floor damaged

105 CMR 451.123

Maintenance: Radiator rusty

*Cells*

No Violations Noted

*Common Area*

FC 4-602.12(B)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

**Lower East**

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

105 CMR 451.123\*

Maintenance: Mold in showers

*Slop Sink Room*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink leaking

105 CMR 451.350

Structural Maintenance: Electrical outlet damaged

105 CMR 451.350

Structural Maintenance: Radiator rusty

*Bathroom*

105 CMR 451.130\*

Plumbing: Plumbing not maintained in good repair, toilet leaking

105 CMR 451.123

Maintenance: Radiator rusty

105 CMR 451.123\*

Maintenance: Baseboard damaged

**Upper East**

*Slop Sink*

105 CMR 451.350\*

Structural Maintenance: Wall damaged

105 CMR 451.130\*

Plumbing: Plumbing not maintained in good repair, sink leaking

*Cells*

105 CMR 451.101

Blankets: Blanket damaged in cell #18

*Showers*

105 CMR 451.353\*

Interior Maintenance: Tile damaged

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

105 CMR 451.123\*

Maintenance: Missing face plate on 1 shower dial

105 CMR 451.123

Maintenance: Door frame damaged

*Bathroom*

105 CMR 451.123

Maintenance: Ceiling vent dusty

105 CMR 451.123

Maintenance: Missing sprayer cap cover on sink

*Interview Room*

No Violations Noted

*Uniform Supply*

No Violations Noted

*Chemical Closet*

105 CMR 451.353

Interior Maintenance: Mop stored in bucket

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

**MINI 5 BUILDING**

105 CMR 451.320\*

Cell Size: Inadequate floor space in cells

105 CMR 451.350\*

Structural Maintenance: Door not rodent and weathertight



### *Booth*

FC 4-501.11(B)\*

105 CMR 451.353\*

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged/dirty  
Interior Maintenance: Ceiling vent dusty

### **Corridor 2**

#### *Showers*

105 CMR 451.350\*

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

Structural Maintenance: Wall damaged  
Maintenance: Soap scum on walls in showers  
Maintenance: Tile damaged in showers  
Maintenance: Ceiling vent dusty  
Maintenance: Missing face plate in shower #1  
Maintenance: Lose face plate in shower #2

#### *Cells*

105 CMR 451.350

105 CMR 451.353

Structural Maintenance: Wall damaged in cell #10  
Interior Maintenance: Paper in light in cell #11

#### *School Area*

No Violations Noted

#### *Office*

No Violations Noted

#### *Weight Room*

No Violations Noted

#### *Chemical Closet*

105 CMR 451.353\*

105 CMR 451.353

Interior Maintenance: Mop stored in bucket  
Interior Maintenance: Standing water left in bucket

#### *T.V Room*

105 CMR 451.350

FC 4-602.12(B)\*

Structural Maintenance: Paint peeling near vent  
Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

### **Corridor 1**

#### *Showers*

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

105 CMR 451.123

Maintenance: Paint peeling  
Maintenance: Walls cracked  
Maintenance: Soap scum on walls in showers  
Maintenance: Wall tiles cracked in showers  
Maintenance: Missing face plate on both showers

#### *Cells*

105 CMR 451.350

Structural Maintenance: Window cracked in cell #14

### **FOOD SERVICE**

#### *Staff Dining*

FC 4-501.11(A)\*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, filter for ice machine dirty

*Staff Line*

FC 4-903.11(B)(1)

FC 4-903.11(A)(2)

FC 4-601.11(A)

Protection of Clean Items, Storing: Plates not stored in the inverted position

Protection of Clean Items, Storing: Single-service items not protected from contamination, utensils left uncovered

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, warming trays dirty

*Bakery Storage*

FC 6-404.11

Location and Placement; Distressed Merchandise: Dented cans not properly segregated

FC 5-205.15(B)

Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, handwash sink leaking

*Dishwasher Area*

FC 6-201.11\*

FC 6-501.12(A)\*

Design, Construction and Installation: Floor not easily cleanable, damaged floor

Maintenance and Operation; Cleaning: Facility not cleaned properly, floors slippery, a lot of standing water

FC 4-501.11(A)

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, dishwasher leaking

FC 4-501.112(A)(2)

Maintenance and Operation, Equipment: Inadequate water temperature in the Hobart mechanical warewashing machine

FC 6-501.12(A)

Maintenance and Operation; Cleaning: Facility not cleaned properly, walls dirty behind 3 bay sink

FC 6-201.16(A)

Design, Construction, and Installation; Cleanability: Ceiling covering not easily cleanable, paint peeling in skylight

*Tray Room*

FC 6-201.16(A)\*

Design, Construction, and Installation; Cleanability: Ceiling covering not easily cleanable, paint peeling in skylight

*Inmate Bathroom*

105 CMR 451.123

Maintenance: Baseboard damaged

*Bakery Area*

No Violations Noted

*Cooler 1*

FC 3-305.11(A)(2)\*

FC 4-903.12 (A)(6)

Preventing Contamination from Premises: Food exposed to dust, fans in cooler dusty

Protection of Clean Items, Storing: Food product stored in an inappropriate location, food stored under condenser lines

*Cooler 2*

FC 3-305.11(A)(2)\*

Preventing Contamination from Premises: Food exposed to dust, fans in cooler dusty

*Cooler 3*

FC 4-501.11(B)\*

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged

*Freezer*

No Violations Noted

*Receiving*

FC 6-202.15(A)(2)\*

Design, Construction, and Installation; Functionality: Outer door not weather and vermin tight

FC 6-501.11\*

Maintenance and Operation; Repairing: Facility not in good repair, wall damaged

*Chemical Closet*

No Violations Noted

*Dry Storage*

No Violations Noted

*Supply Room*

FC 6-202.15(A)(2)\*

Design, Construction, and Installation; Functionality: Outer door not weather and vermin tight

*Can Room*

No Violations Noted

*Control*

105 CMR 451.123

Maintenance: Ceiling vent dusty in bathroom

**SCHOOL**

*Kitchen Area in Hall*

No Violations Noted

*Men's Staff Bathroom*

105 CMR 451.123

Maintenance: Ceiling tiles damaged

105 CMR 451.123

Maintenance: Ceiling vent dusty

*Parole Office*

105 CMR 451.140

Adequate Ventilation: Inadequate ventilation, ceiling vent blocked

*Substance Abuse Office*

105 CMR 451.350

Structural Maintenance: Ceiling tiles water stained

*Women's Room*

105 CMR 451.123

Maintenance: Ceiling vent dusty

*Slop Sink*

105 CMR 451.123

Maintenance: Ceiling vent dusty

**RECEIVING**

*County Lock Up*

Not in use at this time

*ID Room*

No Violations Noted

*Mop Closet*

105 CMR 451.353\*

Interior Maintenance: Mop stored in wet bucket

105 CMR 451.353

Interior Maintenance: Missing light shields

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

*Bathroom, in Records*

No Violations Noted

*Interview Room*

No Violations Noted

## *Records*

No Violations Noted

### *Property Room*

105 CMR 451.350

Structural Maintenance: Wall damaged behind desk

### *Intake Showers*

105 CMR 451.350\*

Structural Maintenance: Holes in the ceiling

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, 1 shower not working

### *Holding Cell #1*

No Violations Noted

### *Holding Cell #2*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, cold water not working

## **MAINTENANCE CORRIDOR**

### *Staff Bathroom*

105 CMR 451.353

Interior Maintenance: Missing ceiling vent

### *Inmate Bathroom*

No Violations Noted

### *Laundry Area*

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged

FC 4-601.11(A)

Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, coffee maker dirty

### *Repair Shop*

105 CMR 451.350\*

Structural Maintenance: Door not rodent and weathertight

### *Welding Area*

105 CMR 451.350\*

Structural Maintenance: Door not rodent and weathertight

105 CMR 451.350

Structural Maintenance: Walls damaged near windows

### *Tool Cage*

105 CMR 451.350

Structural Maintenance: Door not rodent and weathertight

## **MODULAR ADMINISTRATION BUILDING**

### **Lobby**

#### *Waiting Area*

No Violations Noted

#### *Men's Bathroom*

Unable to Inspect – In Use

#### *Female Bathroom*

No Violations Noted

### **Control 3**

105 CMR 451.350\*

Structural Maintenance: Floor damaged

105 CMR 451.350* FC 4-602.12(B)* 105 CMR 451.353*	Structural Maintenance: Baseboard damaged Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty Interior Maintenance: Mop stored in bucket in bathroom
<i>Bathroom</i>	No Violations Noted
<i>Pedestrian Trap</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink
<i>Visiting Area</i> 105 CMR 451.350 105 CMR 451.350	Structural Maintenance: Floor tile damaged Structural Maintenance: Door not rodent and weathertight
<b>Special Services Corridor</b>	
<i>Slop Sink</i> 105 CMR 451.350 105 CMR 451.360	Structural Maintenance: Floor tiles damaged Protective Measures: Drain files observed
<i>Female Locker Room</i> 105 CMR 451.350* 105 CMR 451.130	Structural Maintenance: Ceiling tiles missing Plumbing: Plumbing not maintained in good repair, cold water not working
<i>Male Locker Room</i>	No Violations Noted
<i>Male Bathroom</i> 105 CMR 451.123	Maintenance: Generally dirty
<i>Female Bathroom</i> 105 CMR 451.123*	Maintenance: Baseboard damaged
<i>Operations/Investigation</i>	Unable to access
<i>Mail Room</i> FC 4-602.12(B)*	Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty
<i>Investigations Office</i> FC 3-501.16(B) FC 4-602.12(B) FC 4-903.11(A)(2)	Limitation of Growth of Organisms, Temperature and Time Control: Refrigerator temperature recorded at 47°F Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination, utensils left uncovered
<i>D-Board</i>	No Violations Noted
<i>Phone Room</i>	No Violations Noted
<i>Bubbler</i> 105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, bubbler not working

*Hallway*  
105 CMR 451.350                      Structural Maintenance: Floor tiles damaged in hall of special services corridor

*Dispatch*  
  
No Violations Noted

*Vacant Office*  
105 CMR 451.350\*                      Structural Maintenance: Baseboard damaged  
105 CMR 451.353\*                      Interior Maintenance: Ceiling vent dusty

*Slop Sink Room*  
105 CMR 451.353                      Interior Maintenance: Generally dirty

**2<sup>nd</sup> Floor**

*South Male Bathroom*  
105 CMR 451.123                      Maintenance: Ceiling vent dusty

*South Female Bathroom*  
  
No Violations Noted

*North Male Bathroom*  
  
No Violations Noted

*North Male Bathroom*  
  
No Violations Noted

*Storage Room*  
105 CMR 451.353\*                      Interior Maintenance: Ceiling vent dusty

*Slop Sink Room*  
105 CMR 451.353                      Interior Maintenance: Mop stored in bucket  
105 CMR 451.353                      Interior Maintenance: Water left in bucket

*Computer Lab*  
  
No Violations Noted

*Computer Server Room*  
105 CMR 451.350                      Structural Maintenance: Floor tiles damaged

**MODULAR INFIRMARY**

105 CMR 451.350\*                      Structural Maintenance: Hole in concrete at entrance

**2<sup>nd</sup> Floor**

*Inmate Bathroom #244*  
105 CMR 451.110(A)                      Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink  
105 CMR 451.110(A)                      Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink  
105 CMR 451.123                      Maintenance: Ceiling vent dusty

*Nurse's Station #233*  
  
No Violations Noted

*Officers Station*

No Violations Noted

*Optometrist's Office*

No Violations Noted

*Mop Sink Room*

105 CMR 451.350\*

105 CMR 451.130

Structural Maintenance: Floor damaged

Plumbing: Plumbing not maintained in good repair, sink leaking

*Dentist's Room #253*

No Violations Noted

*Room #241*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

*Room #248*

105 CMR 451.350

Structural Maintenance: Missing ceiling tiles

*Room #250*

No Violations Noted

*Room #238*

105 CMR 451.353

Interior Maintenance: Mop stored in bucket

*Room #242*

105 CMR 451.350\*

Structural Maintenance: Floor tile damaged

*Room #236*

No Violations Noted

*Room #230*

105 CMR 451.350\*

Structural Maintenance: Ceiling damaged

*Women's Bathroom #258*

No Violations Noted

*Men's Bathroom #243*

No Violations Noted

*Holding Cell*

105 CMR 451.350\*

Structural Maintenance: Ceiling unfinished

*Room 254*

105 CMR 451.350\*

Structural Maintenance: Floor damaged

*Inmate Bathroom 244*

No Violations Noted

*Medical Records*

105 CMR 451.350\*

105 CMR 451.350\*

105 CMR 451.123\*

Structural Maintenance: Paint peeling

Structural Maintenance: Ceiling leaking

Maintenance: Mold like substance on walls

*Mop Closet*

No Violations Noted

*Shower Area*

105 CMR 451.123\*

Maintenance: Soap scum on walls in shower

105 CMR 451.123\*

Maintenance: Ceiling damaged

*Captains Office*

No Violations Noted

*Storage Room (near Captain's Office)*

105 CMR 451.353

Interior Maintenance: Missing vent cover

*Ward 206*

No Violations Noted

*Ward 207*

No Violations Noted

*X-Ray Room*

105 CMR 451.350\*

Structural Maintenance: Floor damaged

**1<sup>st</sup> Floor**

*Mod Med Line*

105 CMR 451.350\*

Structural Maintenance: Floor damaged

105 CMR 451.350\*

Structural Maintenance: Door not rodent and weathertight

105 CMR 451.350\*

Structural Maintenance: Baseboard damaged

105 CMR 451.350\*

Structural Maintenance: Wall damaged

*Officer's Office*

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

105 CMR 451.350

Structural Maintenance: Floor tiles missing

*Classrooms*

105 CMR 451.350\*

Structural Maintenance: Floor tiles damaged

105 CMR 451.350\*

Structural Maintenance: Baseboard damaged

105 CMR 451.350\*

Structural Maintenance: Door not rodent and weathertight

105 CMR 451.350\*

Structural Maintenance: Ceiling tiles missing

105 CMR 451.350\*

Structural Maintenance: Wall damaged

105 CMR 451.350

Structural Maintenance: Door rotted

*Role Call Room*

105 CMR 451.350\*

Structural Maintenance: Floor damaged

105 CMR 451.350\*

Structural Maintenance: Door not rodent and weathertight

105 CMR 451.350\*

Structural Maintenance: Ceiling water damaged

105 CMR 451.350\*

Structural Maintenance: Door rotted (outside)

*Old Kitchen*

105 CMR 451.350\*

Structural Maintenance: Wall damaged

105 CMR 451.350\*

Structural Maintenance: Floor damaged

105 CMR 451.350\*

Structural Maintenance: Floor tiles missing and damaged

105 CMR 451.350\*

Structural Maintenance: Ceiling damaged

105 CMR 451.350\*

Structural Maintenance: Area not rodent and weathertight



105 CMR 451.353\*  
105 CMR 451.353\*

Interior Maintenance: Walls dirty  
Interior Maintenance: Debris everywhere

## **GYM BUILDING**

105 CMR 451.350\*  
105 CMR 451.350\*  
105 CMR 451.353\*

Structural Maintenance: Area not rodent and weathertight  
Structural Maintenance: Wall paint peeling  
Interior Maintenance: Bubbler not working

### *Staff Bathroom*

Unable to Access

### *Inmate's Bathroom*

105 CMR 451.110(A)\*  
105 CMR 451.110(A)\*

Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink  
Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

### *Control Booth*

No Violations Noted

### *Room #106*

105 CMR 451.350

Structural Maintenance: Wall paint peeling

### *Room #107*

No Violations Noted

### *Room #108*

No Violations Noted

### *Room #105*

Unable to Access

## **TOWER**

### *1<sup>st</sup> Floor*

105 CMR 451.353\*  
105 CMR 451.353\*

Interior Maintenance: Area dirty with trash and litter on the floor  
Interior Maintenance: Loose wires and uncovered junction box

### *2<sup>nd</sup> Floor*

105 CMR 451.123\*  
105 CMR 451.126\*  
105 CMR 451.350\*  
105 CMR 451.350\*  
105 CMR 451.353\*

Maintenance: Floor dirty  
Hot Water: Hot water temperature recorded at 106°F  
Structural Maintenance: Wall damaged  
Structural Maintenance: Ceiling damaged  
Interior Maintenance: Mop stored in bucket

### *3<sup>rd</sup> Floor*

FC 4-602.12(B)\*  
FC 4-204.112(A)\*  
105 CMR 451.350  
105 CMR 451.350  
105 CMR 451.350  
105 CMR 451.353  
105 CMR 451.350  
FC 4-903.11(A)(2)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty  
Design and Construction, Functionality: No functioning thermometer in refrigerator  
Structural Maintenance: Holes in glass  
Structural Maintenance: Wall paint peeling  
Structural Maintenance: Wall damaged  
Interior Maintenance: Missing light shields  
Structural Maintenance: Exposed phone wires  
Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

FC 4-501.11(B)	Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged
FC 4-204.112(A)	Design and Construction, Functionality: No functioning thermometer in refrigerator

## **MODULAR VISITING AREA**

### *Visiting*

105 CMR 451.350*	Structural Maintenance: Floor damaged
105 CMR 451.350*	Structural Maintenance: Area not rodent and weathertight, door threshold rotted
105 CMR 451.350*	Structural Maintenance: Wall damaged near back door
105 CMR 451.350	Structural Maintenance: Missing ceiling tiles in social worker area for inmates

### *Bathroom*

Unable to Access

### *Slop Sink*

105 CMR 451.350*	Structural Maintenance: Floor tiles missing
------------------	---

### *IP Break Room*

105 CMR 451.350*	Structural Maintenance: Floor damaged
FC 4-602.12(B)*	Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty
FC 4-903.11(A)(2)	Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

### *Officer's Bathroom*

105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, cold water not working
105 CMR 451.123	Maintenance: Ceiling vent dusty

### **Receiving**

105 CMR 451.360	Protective Measures: Rodent dropping observed
-----------------	---

### *Waiting Area*

105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, bubbler not working
105 CMR 451.350*	Structural Maintenance: Door not rodent and weathertight
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, bubbler not working
105 CMR 451.350	Structural Maintenance: Baseboard damaged at rear entrance
105 CMR 451.350	Structural Maintenance: Wall damaged

### *Clothing Room*

105 CMR 451.350*	Structural Maintenance: Ceiling leaking
105 CMR 451.350*	Structural Maintenance: Wall damaged
105 CMR 451.350*	Structural Maintenance: Wall peeling
105 CMR 451.350*	Structural Maintenance: Floor tiles missing
105 CMR 451.350*	Structural Maintenance: Ceiling damaged
105 CMR 451.353*	Interior Maintenance: Appearance of a mold like substance

### *Personal Property*

No Violations Noted

### *Uniform Storage*

No Violations Noted

### *Chemical Room*

105 CMR 451.353*	Interior Maintenance: Mop stored in bucket
105 CMR 451.353	Interior Maintenance: Ceiling vent dusty

*Small Clothing Room*

105 CMR 451.350

105 CMR 451.350

105 CMR 451.350

Structural Maintenance: Wall damaged

Structural Maintenance: Ceiling tiles damaged

Structural Maintenance: Floor tiles damaged

*Urinalysis Storage*

No Violations Noted

*Slop Sink Room*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink leaking

*Holding Cells*

105 CMR 451.353

Interior Maintenance: Cell #107 generally dirty

*Staff Bathroom*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Inmate Bathroom*

105 CMR 451.353\*

105 CMR 451.110(A)

105 CMR 451.110(A)

Interior Maintenance: Ceiling vent not secure to the ceiling

Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

*Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

*Break Area*

No Violations Noted

**VOC LAUNDRY**

105 CMR 451.350

Structural Maintenance: Baseboard damaged at entry

**1<sup>st</sup> Floor**

*Laundry*

105 CMR 451.130\*

105 CMR 451.130

105 CMR 451.350\*

105 CMR 451.353

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, 1 washer leaking

Plumbing: Plumbing not maintained in good repair, 1 washer broken

Structural Maintenance: Ceiling damaged

Interior Maintenance: Mold like substance build-up behind washers

Plumbing: Plumbing not maintained in good repair, the washers are draining into trough, when they drain the water sprays everywhere

*Chemical Storage*

Unable to access

*Inmate Bathroom*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink leaking

*Staff Bathroom*

105 CMR 451.130

105 CMR 451.353

Plumbing: Plumbing not maintained in good repair, missing cap on hot water faucet

Interior Maintenance: Ceiling vent dusty

*Janitor's Room*

No Violations Noted

## *Library*

Unable to Access

## *IT Break Area*

FC 4-903.11(A)(2)

Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

FC 4-204.112(A)

Design and Construction, Functionality: No functioning thermometer in refrigerator

## *Hallway*

105 CMR 451.350\*

Structural Maintenance: Area not rodent and weathertight

## **2<sup>nd</sup> Floor**

### *Room 203*

105 CMR 451.350\*

Structural Maintenance: Ceiling tiles damaged and water stained

## **H BUILDING**

105 CMR 451.321\*

Cell Size: Inadequate floor space in cells

105 CMR 451.343\*

Electric Fixtures in Cell: No electrical outlet in cell

### *Control Booth*

105 CMR 451.350\*

Structural Maintenance: Floor tiles missing in bathroom

FC 4-602.12(B)\*

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty

### *Cells*

105 CMR 451.141

Screens: Screen damaged in cell #111

105 CMR 451.353

Interior Maintenance: Vents blocked in cell #102, 104, 107-119, 123-139, 142-144, 147-150, 152, 154 & 156-160

### *Showers*

105 CMR 451.123\*

Maintenance: Soap scum on walls in showers

105 CMR 451.350\*

Structural Maintenance: Baseboard damaged

105 CMR 451.123\*

Maintenance: Mold in showers

105 CMR 451.123\*

Maintenance: Paint peeling

## **I & J BUILDING**

105 CMR 451.321\*

Cell Size: Inadequate floor space in cells

105 CMR 451.343\*

Electric Fixtures in Cell: No electrical outlet in cell

### *Control Booth*

FC 4-602.12(B)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

FC 4-501.11(B)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets dirty

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

FC 3-501.16(B)

Limitation of Growth of Organisms, Temperature and Time Control: Refrigerator temperature recorded at 46 °F

## **I Side**

### *Cells*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink doesn't shut off in cell #201

105 CMR 451.353 Interior Maintenance: Vents blocked in cell #163, 171, 173, 174, 177, 179-187,190-193, 195, 196, 198-202 & 207-220

*Showers*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers  
105 CMR 451.123\* Maintenance: Damaged baseboards  
105 CMR 451.123\* Maintenance: Paint peeling  
105 CMR 451.123\* Maintenance: Missing dial in shower #5  
105 CMR 451.360 Protective Measures: Drain flies observed  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, handicapped shower broken

*Chemical Room*

105 CMR 451.353\* Interior Maintenance: Mop stored in bucket  
105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

*Interview Room*

105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

**J Side**

*Cells*

105 CMR 451.141 Screens: Screen damaged in cell #241 and 253  
105 CMR 451.353 Interior Maintenance: Ceiling vents blocked in cell #221-226, 229-231, 236, 242, 245, 252, 253 & 256-280

*Showers*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers  
105 CMR 451.123\* Maintenance: Missing face plate on shower  
105 CMR 451.123\* Maintenance: Mold like substance on walls  
105 CMR 451.123\* Maintenance: Floor not sealed, cracked  
105 CMR 451.123 Maintenance: Tile damaged

*Chemical Area*

105 CMR 451.353 Interior Maintenance: Drain cover loose  
105 CMR 451.353 Interior Maintenance: Water left in bucket

*Interview Room*

Unable to access

**K & L BUILDING**

105 CMR 451.321\* Cell Size: Inadequate floor space in cells  
105 CMR 451.343\* Electric Fixtures in Cell: No electrical outlet in cell

*Control Booth*

FC 4-602.12(B)\* Cleaning of Equipment and Utensils; Frequency: Interior of microwave ovens dirty  
FC 4-501.11(A) Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, microwave damaged  
FC 3-501.16(B) Limitation of Growth of Organisms, Temperature and Time Control: Refrigerator temperature recorded at 46<sup>0</sup>F  
FC 4-204.112(A) Design and Construction, Functionality: No functioning thermometer in refrigerator, thermometer broken  
FC 4-601.11(A) Cleaning of Equipment and Utensils, Objective: Food contact surface dirty, refrigerator  
105 CMR 451.353 Interior Maintenance: Ceiling vent dusty

## **K Side**

### *Cells*

105 CMR 451.350 Structural Maintenance: Uncovered/missing electrical cover in cell #313-320, 323 & 332  
105 CMR 451.103 Mattresses: Mattress damaged in cell #281  
105 CMR 451.101 Blankets: Blanket damaged in cell #285  
105 CMR 451.353 Interior Maintenance: Vents blocked in cell #281, 286, 287, 294, 299, 303-306, 308, 310-320, 324-328, 331, 333-335, 339 & 340

### *Showers*

105 CMR 451.123\* Maintenance: Baseboard damaged  
105 CMR 451.123\* Maintenance: Tiles damaged  
105 CMR 451.123 Maintenance: Shower curtains damaged  
105 CMR 451.123 Maintenance: Soap scum on walls in showers  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, 6 showers have no hot water

### *Chemical Room*

105 CMR 451.353\* Interior Maintenance: Standing water left in bucket  
105 CMR 451.353\* Interior Maintenance: Mop stored in bucket  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, sink leaking

### *Interview Room*

No Violations Noted

## **L Side**

105 CMR 451.350\* Structural Maintenance: Ceiling damaged

### *Cells*

105 CMR 451.353 Interior Maintenance: Vents blocked in cell #341, 342, 348, 354, 355, 362, 365, 371, 374-377, 379, 383, 385, 386, 389, 390, 392, 395, 396 & 399  
105 CMR 451.350 Structural Maintenance: Uncovered electrical outlet in cell #375, 380 & 381

### *Showers*

105 CMR 451.123\* Maintenance: Soap scum on walls in showers  
105 CMR 451.123\* Maintenance: Baseboards damaged  
105 CMR 451.123\* Maintenance: Missing face plate in shower #4 & 9  
105 CMR 451.130\* Plumbing: Plumbing not maintained in good repair, handicapped shower leaks  
105 CMR 451.123\* Maintenance: Appearance of mold in showers  
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, 6 showers have no hot water

### *Chemical Room*

105 CMR 451.353 Interior Maintenance: Mop stored in bucket

### *Interview Room*

No Violations Noted

## **WORK RELEASE**

### *Control Booth*

FC 4-602.12(B)\* Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty  
FC 4-501.11(B) Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged

*Main Hallway*

105 CMR 451.353\*  
105 CMR 451.350\*

Interior Maintenance: Floor tiles damaged  
Structural Maintenance: Windows cracked

*Rec. Area (left)*

105 CMR 451.350  
105 CMR 451.353  
105 CMR 451.353  
FC 4-602.12(B)

Structural Maintenance: Baseboard damaged  
Interior Maintenance: Mop stored in bucket in closet  
Interior Maintenance: Missing light shield  
Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

*Bathroom (left)*

Unable to Inspect – Occupied

*Slop Sink Room (left)*

No Violations Noted

*Showers (left)*

105 CMR 451.123\*  
105 CMR 451.123  
105 CMR 451.123  
105 CMR 451.121(A)\*

Maintenance: 1 showers leaking  
Maintenance: Soap scum on walls in showers  
Maintenance: Ceiling tile damage  
Privacy: No privacy partition between showers

*Showers (right)*

105 CMR 451.123\*  
105 CMR 451.130\*  
105 CMR 451.121(A)\*  
105 CMR 451.130  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Soap scum on walls in showers  
Plumbing: Plumbing not maintained in good repair, showers leaking  
Privacy: No privacy partition between showers  
Plumbing: Plumbing not maintained in good repair, 2 showers not working  
Maintenance: Tile damage  
Maintenance: Ceiling tile damaged

*Staff Bathroom*

105 CMR 451.110(A)  
105 CMR 451.123

Hygiene Supplies at Toilet and Handwash Sink: No soap at handwash sink  
Maintenance: Ceiling damaged

*Laundry*

105 CMR 451.353\*

Interior Maintenance: Lint and debris behind dryer

*Chow*

No Violations Noted

*Day Room (right)*

105 CMR 451.350\*

Structural Maintenance: Baseboards damaged

*Inmate Bathroom*

105 CMR 451.130  
105 CMR 451.130  
105 CMR 451.123

Plumbing: Plumbing not maintained in good repair, hot water not working at last sink  
Plumbing: Plumbing not maintained in good repair, faucet leaking at 3<sup>rd</sup> sink  
Maintenance: Wall damaged behind urinal

**WAREHOUSE BUILDING**

105 CMR 451.350

Structural Maintenance: Door not rodent and weathertight

**Staff Gym**

No Violations Noted

*Female Bathroom*  
105 CMR 451.123

Maintenance: Ceiling vent dusty

*Men's Bathroom*

In Use -- Unable to Access

**Warehouse**  
105 CMR 451.350\*

Structural Maintenance: Wall damaged on the exterior

*Break Area*

No Violations Noted

*Inmate Bathroom*  
105 CMR 451.123

Maintenance: Sink drain cover missing

*Staff Bathroom*

No Violations Noted

*Chemical Room*  
105 CMR 451.353\*

Interior Maintenance: Mop stored in bucket

*Walk in Freezer*  
FC 4-501.11(A)\*

Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, interior door frame damaged

*Exterior Cooler 2*  
105 CMR 451.350\*  
105 CMR 451.350

Structural Maintenance: Damaged baseboards  
Structural Maintenance: Door frame damaged

*Exterior Cooler 1*  
FC 3-305.11(A)(2)\*

Preventing Contamination from Premises: Food exposed to dust, fans in cooler dusty

## **GARAGE**

**Transportation Office**  
105 CMR 451.350

Structural Maintenance: Area not rodent and weathertight

*Kitchen Area*  
FC 4-602.12(B)\*

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty

*Inmate Bathroom*  
105 CMR 451.350\*  
105 CMR 451.123

Structural Maintenance: Wall damaged  
Maintenance: Ceiling tiles water damaged

*Staff Bathroom*  
105 CMR 451.123\*  
105 CMR 451.353\*  
105 CMR 451.123  
105 CMR 451.123

Maintenance: Wall damaged behind toilet  
Interior Maintenance: Ceiling vent dusty  
Maintenance: Walls dirty  
Maintenance: Generally dirty

*Bays*

No Violations Noted

*Key Control*

No Violations Noted



MSF

Vacant

ANNEX

105 CMR 451.320\*

Cell Size: Inadequate floor space

*Control Booth*

FC 4-602.12(B)\*

105 CMR 451.350\*

FC 4-903.11(A)(2)

Cleaning of Equipment and Utensils; Frequency: Interior of microwave oven dirty  
Structural Maintenance: Ceiling tiles water stained  
Protection of Clean Items, Storing: Single-service items uncovered and not protected from contamination

*Female Staff Bathroom*

105 CMR 451.126\*

Hot Water: Hot water temperature recorded at 100°F

*Male Staff Bathroom*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Chemical Cage*

105 CMR 451.353

Interior Maintenance: Mop stored in bucket

*Male Visiting*

105 CMR 451.353

Interior Maintenance: Ceiling vent dusty

*Food Area*

FC 4-501.11(B)\*

105 CMR 451.353\*

105 CMR 451.110(B)\*

105 CMR 451.350\*

FC 3-304.12(A)

Maintenance and Operation, Equipment: Equipment components not maintained in a state of good repair, refrigerator gaskets damaged  
Interior Maintenance: Floor drain damaged, trip hazard  
Hygiene Supplies at Toilet and Handwash Sink: No waste receptacle at handwash sink  
Structural Maintenance: Ceiling tiles water damaged  
Preventing Contamination from Utensils: Service utensils handle stored below the food and container line

*Shower Area*

105 CMR 451.140\*

105 CMR 451.123\*

105 CMR 451.353\*

Adequate Ventilation: Inadequate ventilation damaged ceiling tiles  
Maintenance: Soap scum on walls in showers  
Interior Maintenance: Paint peeling

*Medical*

No Violations Noted

*Classroom*

No Violations Noted

*Toilet Area*

105 CMR 451.353\*

Interior Maintenance: Ceiling vent dusty

*Sink Area*

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, 3 sinks not working

*Laundry Room*

105 CMR 451.130

105 CMR 451.353

105 CMR 451.353

Plumbing: Plumbing not maintained in good repair, washer leaking  
Interior Maintenance: Debris build-up behind dryer  
Interior Maintenance: Dryer not vented to the exterior

## Observations and Recommendations

- The inmate population was 1255 at the time of inspection


This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please indicate next to each entry on the inspection report a plan of correction. Said plan of correction must be submitted within ten working days of receiving this report and should detail the specific steps that will be taken and the date of expected compliance. The plan of correction should be submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at [www.mass.gov/dph/dcs](http://www.mass.gov/dph/dcs) and click on "Community Sanitation Regulations" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at [www.mass.gov/dph/fpp](http://www.mass.gov/dph/fpp) and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Amy Riordan  
Environmental Health Inspector, CSP, BEH

cc: Suzanne K. Condon, Associate Commissioner, Director, BEH  
Steven Hughes, Director, CSP, BEH  
JudyAnn Bigby, MD, Secretary, Executive Office of Health and Human Services  
Luis S. Spencer, Commissioner, DOC  
Dennis Dolye, FSO  
West Boylston Board of Health  
Clerk, Massachusetts House of Representatives  
Clerk, Massachusetts Senate  
Mary Elizabeth Heffernan, EOPS