



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
Community Sanitation Program
180 Beaman Street, West Boylston, MA 01583
Phone: 508-792-7880 Fax: 508-792-7706
TTY: 508-835-9796

CHARLES D. BAKER
Governor

KARYN E. POLITO
Lieutenant Governor

MARYLOU SUDDERS
Secretary

MONICA BHAREL, MD, MPH
Commissioner

Tel: 617-624-6000
www.mass.gov/dph

October 25, 2017

David H. Tuttle, Superintendent
Worcester County House of Corrections and Jail
5 Paul X. Tivnan Drive
West Boylston, MA 01583

Re: Facility Inspection - Worcester County House of Corrections and Jail, West Boylston

Dear Superintendent Tuttle:

In accordance with M.G.L. c. 111, §§ 5, 20, and 21, as well as Massachusetts Department of Public Health (Department) Regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities; 105 CMR 480.000: Storage and Disposal of Infectious or Physically Dangerous Medical or Biological Waste (State Sanitary Code, Chapter VIII); 105 CMR 590.000: Minimum Sanitation Standards for Food Establishments (State Sanitary Code Chapter X); the 1999 Food Code; 105 CMR 520.000 Labeling; and 105 CMR 205.000 Minimum Standards Governing Medical Records and the Conduct of Physical Examinations in Correctional Facilities; I conducted an inspection of the Worcester County House of Corrections and Jail on October 4, 5, and 6, 2017 accompanied by Patrick Ryan, Environmental Health & Safety Officer; Diane Cook, Program Development Coordinator; Captain Jason Butland, and Kerry Wagner, Community Sanitation Program. Violations noted during the inspection are listed below including 305 repeat violations:

HEALTH AND SAFETY VIOLATIONS

(* indicates conditions documented on previous inspection reports)

Entrance

Waiting Area

No Violations Noted

Fisher Conference Room

No Violations Noted

Hallway

No Violations Noted

Assistant Deputy Superintendent's Office

No Violations Noted

Deputy's Office

No Violations Noted

Staff Locker Room

No Violations Noted

Staff Bathroom

No Violations Noted

Control Room

105 CMR 451.353*

Interior Maintenance: Area around microwave dirty

105 CMR 451.200

Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty

Control Bathroom

105 CMR 451.123*

Maintenance: Handwash sink dirty

105 CMR 451.123*

Maintenance: Faucet fixture corroded

105 CMR 451.123

Maintenance: Light shield missing

Key Room

No Violations Noted

Herman Building

105 CMR 451.320*

Cell Size: Inadequate floor space in all cells

105 CMR 451.343*

Electric Fixtures in Cell: No electrical outlet in all cells

A2 Block**Control Booth**

105 CMR 451.353*

Interior Maintenance: Floor dirty

105 CMR 451.353

Interior Maintenance: Ceiling tiles loose

Control Bathroom

105 CMR 451.123

Maintenance: Handwash sink dirty

105 CMR 451.117

Toilet Fixtures: Toilet fixtures dirty

Day Room

No Violations Noted

Chemical Storage Room

No Violations Noted

Paper Goods Storage

No Violations Noted

Staff Room

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

Slop Sink Room (Upstairs)

105 CMR 451.353

Interior Maintenance: Slop sink dirty

Cells (Upstairs)

105 CMR 451.353*

Interior Maintenance: Debris on light shield in cell # 33

105 CMR 451.353*

Interior Maintenance: Floor paint peeling in cell # 33, 35, 37, and 45

105 CMR 451.353

Interior Maintenance: Floor paint peeling in cell # 41

Showers (Upstairs)

No Violations Noted

Slop Sink (Downstairs)

No Violations Noted

Cells (Downstairs)

105 CMR 451.353*

Interior Maintenance: Debris on light shield in cell # 55 and 62

105 CMR 451.353*

Interior Maintenance: Floor paint peeling in cell # 52 and 56

105 CMR 451.353

Interior Maintenance: Floor paint peeling in cell # 50 and 51

Showers (Downstairs)

105 CMR 451.123*

Maintenance: Bottom of door frame rusted in shower # 1

Hallway

No Violations Noted

Storage Closet

No Violations Noted

A1 Block

Control Booth

105 CMR 451.353*

Interior Maintenance: Ceiling tiles water damaged

105 CMR 451.353*

Interior Maintenance: Floor dirty

105 CMR 451.353

Interior Maintenance: Ceiling tiles loose

Control Bathroom

105 CMR 451.123*

Maintenance: Floor dirty

105 CMR 451.123*

Maintenance: Floor paint damaged

Day Room

No Violations Noted

Room # 6

No Violations Noted

Room # 5

No Violations Noted

Room # 4

No Violations Noted

Room # 3

No Violations Noted

Room # 2

No Violations Noted

Room # 1

No Violations Noted

Slop Sink (Upstairs)

No Violations Noted

Cells (Upstairs)

105 CMR 451.123*

Maintenance: Toilet damaged in cell # 16

Showers (Upstairs)

No Violations Noted

Slop Sink (Downstairs)

No Violations Noted

Cells (Downstairs)

105 CMR 451.353*

Interior Maintenance: Floor paint peeling in cell # 18, 22, and 29

105 CMR 451.353

Interior Maintenance: Floor paint peeling in cell # 21 and 31

Showers (Downstairs)

No Violations Noted

Rec Area

Unable to Inspect – Under Construction

MAXIB

105 CMR 451.320*

Cell Size: Inadequate floor space in all cells

Control

105 CMR 451.353

Interior Maintenance: Ceiling tiles water damaged outside control

Control Bathroom

105 CMR 451.123*

Maintenance: Floor dirty

105 CMR 451.123*

Maintenance: Wall damaged

Lower Right Tier

Day Room

No Violations Noted

Slop Sink

No Violations Noted

Showers

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Wall vent dusty in cell # 104, 110, 120, 122, 130, 136, and 138

105 CMR 451.353

Interior Maintenance: Wall vent dusty in cell # 126 and 132

Lower Left Tier

Day Room

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Wall vent dusty in cell # 107, 113, 129, 141, and 147

105 CMR 451.353

Interior Maintenance: Wall vent dusty in cell # 109, 115, and 145

105 CMR 451.353*

Interior Maintenance: Wall vent blocked in cell # 149

105 CMR 451.353

Interior Maintenance: Wall vent blocked in cell # 125

105 CMR 451.353*

Interior Maintenance: Wall paint damaged by toilet in cell # 131

Showers

No Violations Noted

Slop Sink

No Violations Noted

Chemical Closet

No Violations Noted

Lower Disciplinary Unit

Unable to Inspect –Not in Use

Upper Left Tier

Day Room

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Wall vent dusty in cell # 303 and 305

Slop Sink

No Violations Noted

Showers

Unable to Inspect –In Use

Upper Disciplinary Unit

105 CMR 451.353*

Interior Maintenance: Wall paint damaged in cell # 1 and 2

Upper Right Tier

Day Room

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Wall vent dusty in cell # 330 and 346

105 CMR 451.353

Interior Maintenance: Wall vent dusty in cell # 332

Showers

105 CMR 451.123

Maintenance: Epoxy damaged on wall in shower # 1

Slop Sink

No Violations Noted

Chapel

No Violations Noted

Office (Right of Altar)

Unable to Inspect – Locked

Health Services

Interview Room # 1

No Violations Noted

Interview Room # 2

No Violations Noted

Infirmery Ward Bunk Room

105 CMR 451.320*

Cell Size: Inadequate floor space in all cells

Bathroom & Shower

105 CMR 451.123

Maintenance: Shower curtain dirty

105 CMR 451.123

Maintenance: Wall tiles rust stained in shower

105 CMR 451.123

Maintenance: Ceiling vent paint peeling

Examiner's Room

No Violations Noted

Nurse's Room

No Violations Noted

Pharmacy

No Violations Noted

Mental Health Offices

No Violations Noted

Break Room

No Violations Noted

Supply Room w/o Sink

No Violations Noted

Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Supply Closet with Sink

105 CMR 451.353

Interior Maintenance: Wet mop stored in bucket

Biohazard Storage

No Violations Noted

Central Control

105 CMR 451.200*

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator

Control Bathroom

105 CMR 451.123*

Maintenance: Wall dirty near sink

105 CMR 451.123*

Maintenance: Handwash sink dirty

Property

No Violations Noted

Gymnasium

Slop Sink Closet (Hallway)

No Violations Noted

Basketball Court

105 CMR 451.350*	Structural Maintenance: Floor damaged
105 CMR 451.350*	Structural Maintenance: Wall damaged
105 CMR 451.350*	Structural Maintenance: Ceiling damaged
105 CMR 451.353*	Interior Maintenance: Ceiling paint peeling
105 CMR 451.353*	Interior Maintenance: Gym equipment padding damaged

Bathroom with Showers (Unable to Inspect Showers -- Locked)

No Violations Noted

Booth

105 CMR 451.353*	Interior Maintenance: Air conditioning unit not vented to the exterior
105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, disposable silverware not stored with handles up

Staff Bathroom

No Violations Noted

Bathroom without Showers

Unable to Inspect – Not in Use

VISITING ROOM

Inmate Visiting Side

105 CMR 451.353*	Interior Maintenance: Wall damaged near phone in booth # 19 and 20
105 CMR 451.353*	Interior Maintenance: Counter top damaged in booth # 1, 10, and 14
105 CMR 451.353	Interior Maintenance: Counter top damaged in booth # 12

Non-Inmate Visiting Side

105 CMR 451.353*	Interior Maintenance: Floor paint damaged throughout area
105 CMR 451.353*	Interior Maintenance: Wall damaged near phone in booth # 1
105 CMR 451.353	Interior Maintenance: Wall damaged near phone in booth # 2
105 CMR 451.353	Interior Maintenance: Wall panel damaged in booth # 9

Female Handicapped Bathroom

105 CMR 451.123*	Maintenance: Mirror rusted
105 CMR 451.124	Water Supply: Insufficient water supply in quantity and pressure at handwash sink

Male Handicapped Bathroom

105 CMR 451.124*	Water Supply: Insufficient hot and cold water supply in quantity and pressure at handwash sink
------------------	--

Female Bathroom

No Violations Noted

Male Bathroom

105 CMR 451.123*	Maintenance: Wall paint damaged near urinal
------------------	---

MAXIC

105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
------------------	--

Control Booth

105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functional thermometer in small refrigerator
105 CMR 451.353*	Interior Maintenance: Light shield not secured to light fixture
105 CMR 451.353	Interior Maintenance: Light shield missing above door

Booth Bathroom

105 CMR 451.123*	Maintenance: Bathroom generally dirty
105 CMR 451.123*	Maintenance: Faucet fixture corroded
105 CMR 451.123*	Maintenance: Handwash sink dirty
105 CMR 451.123*	Maintenance: Toilet dirty

Upper Tier

Left-Side Day Room

No Violations Noted

Right-Side Day Room

No Violations Noted

Cells

105 CMR 451.353*	Unable to Inspect Cell # 448 – Not in Use
105 CMR 451.353	Interior Maintenance: Ceiling paint peeling in cell # 430
105 CMR 451.130	Interior Maintenance: Ceiling paint peeling in cell # 437
	Plumbing: Toilet not kept in repair, toilet continually running in cell # 424

Showers

No Violations Noted

Slop Sink

No Violations Noted

Old Segregation

Unable to Inspect --Not in Use

Lower Tier

Left-Side Day Room

No Violations Noted

Right-Side Day Room

No Violations Noted

Cells

105 CMR 451.103	Mattresses: Mattress damaged in cell # 245, 248, and 252
-----------------	--

Slop Sink

No Violations Noted

Showers

105 CMR 451.123	Maintenance: Wall paint peeling in shower # 1
-----------------	---

Segregation

Unable to Inspect –Not in Use

Chemical Area

No Violations Noted

Deignan Building

105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
------------------	--

Control Booth

No Violations Noted

Control Booth Bathroom

105 CMR 451.123

Maintenance: Handwash sink dirty

Upper West

Showers

105 CMR 451.123*

Maintenance: Floor tiles damaged outside of showers

Cells

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged in cell # 49 and 64

105 CMR 451.353*

Interior Maintenance: Light shield damaged in cell # 53

Slop Sink Room

105 CMR 451.353*

Interior Maintenance: Wall dirty around slop sink

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, slop sink continuously running

Bathroom

105 CMR 451.123*

Maintenance: Sink basin damaged at sink # 1 and 2

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink # 1

Lower West

Showers

No Violations Noted

Bathroom

105 CMR 451.123*

Maintenance: Floor paint peeling

105 CMR 451.123*

Maintenance: Sink basin damaged at sink # 1

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, hot water faucet not working at handwash sink # 1

105 CMR 451.123

Maintenance: Ceiling vent dusty

105 CMR 451.123

Maintenance: Heater rusted

Cells

105 CMR 451.353*

Interior Maintenance: Light shield damaged in cell # 40

105 CMR 451.353*

Interior Maintenance: Wooden door damaged in cell # 41

Common Area

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged in lower common area

Interview Room

No Violations Noted

Dry Storage

No Violations Noted

Chemical Closet

No Violations Noted

Lower East

Showers

105 CMR 451.123

Maintenance: Floor tiles damaged outside shower # 2

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 1 leaking

Bathroom

105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, handwash sink # 4 leaking

Cells

105 CMR 451.353* Interior Maintenance: Floor damaged in cell # 2
105 CMR 451.353* Interior Maintenance: Light shield damaged in cell # 16
105 CMR 451.353 Interior Maintenance: Light shield missing in cell # 7

Slop Sink Room

105 CMR 451.353* Interior Maintenance: Walls around slop sink dirty
105 CMR 451.353* Interior Maintenance: Wall paint around slop sink damaged
105 CMR 451.130 Plumbing: Plumbing not maintained in good repair, slop sink faucet leaking

Upper East

Slop Sink Room

105 CMR 451.353 Interior Maintenance: Light shield missing
105 CMR 451.353* Interior Maintenance: Wall paint damaged
105 CMR 451.353* Interior Maintenance: Ceiling vent dusty
105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, drain cover missing on slop sink

Cells

105 CMR 451.353* Interior Maintenance: Wooden door damaged in cell # 32

Showers

105 CMR 451.123* Maintenance: Access panel rusted in shower # 2

Bathroom

105 CMR 451.123 Maintenance: Unfinished wood on ceiling above toilet # 2

Mini 5 Building

105 CMR 451.320* Cell Size: Inadequate floor space in all cells

Booth

No Violations Noted

Booth Bathroom

Unable to Inspect – In Use

Corridor 2 (Right Side)

TV Room

No Violations Noted

Showers

105 CMR 451.123* Maintenance: Ceiling paint peeling in shower # 1
105 CMR 451.123* Maintenance: Light shield missing in shower # 1
105 CMR 451.123 Maintenance: Shower stall # 2 dirty

Cells

105 CMR 451.353* Interior Maintenance: Wall paint damaged in cell # 10
105 CMR 451.350 Structural Maintenance: Wall damaged above top bunk in cell # 9
105 CMR 451.350 Structural Maintenance: Wall damaged by toilet in cell # 9

Middle Corridor

Chow Area

No Violations Noted

Weight Room

105 CMR 451.353

Interior Maintenance: Wall paint damaged

105 CMR 451.353

Interior Maintenance: Floor paint damaged

105 CMR 451.353

Interior Maintenance: Gym equipment padding damaged

Chemical Closet

105 CMR 451.353

Interior Maintenance: Light shield missing

Office

No Violations Noted

Corridor 1 (Left Side)

Hallway

No Violations Noted

Showers (Unable to Inspect – Shower # 2 under Construction)

105 CMR 451.123

Maintenance: Ceiling paint damaged

Office with Bathroom

105 CMR 451.123

Maintenance: Light shield not secure

Cells

No Violations Noted

Food Service

Staff Dining Room

No Violations Noted

Staff Serving Line

FC 3-501.16(A)

Limitation of Growth of Organisms, Temperature and Time Control: Potentially hazardous food not held at the proper hot holding temperature, rice and beans recorded at 101°F

Spice Closet

FC 3-302.12

Preventing Food and Ingredient Contamination: Unlabeled food containers

Staff Bakery

No Violations Noted

Inmate Food Prep Area

FC 6-501.11*

Maintenance and Operation; Repairing: Facility not in good repair, floor tiles cracked

Produce Cooler

No Violations Noted

Milk Cooler

No Violations Noted

<i>Prep Cooler</i> FC 6-501.11*	Maintenance and Operation; Repairing: Facility not in good repair, floor tiles damaged
FC 6-501.11	Maintenance and Operation; Repairing: Facility not in good repair, 1 light out
<i>Tool Storage</i>	No Violations Noted
<i>Control</i>	No Violations Noted
<i>Control Bathroom</i> 105 CMR 451.123	Maintenance: Handwash sink dirty
<i>Freezer</i> FC 4-501.11(A)	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, 1 fan not working
<i>Dry Goods</i>	No Violations Noted
<i>Area outside of Dry Goods Storage</i>	No Violations Noted
<i>Receiving Area</i> FC 4-501.11(A)*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, exterior of several food carts damaged
<i>Chemical Closet</i>	No Violations Noted
<i>Dishwasher Area</i> FC 5-205.15(B) FC 4-204.115	Plumbing System, Operations and Maintenance: Plumbing system not maintained in good repair, single bay sink near warewash machine leaking Design and Construction, Functionality: Thermometer not functioning properly on warewashing machine, rinse gauge temperature not working
<i>3-Bay Sink # 1 and 2</i>	No Violations Noted
<i>Pasta Room</i>	No Violations Noted
<i>Can Room</i>	No Violations Noted
<i>Inmate Serving Area</i>	No Violations Noted
<i>Inmate Bathroom</i> 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Maintenance: Toilet dirty Maintenance: Handwash sink dirty Maintenance: Paper towel dispenser broken

School

Office (near entrance)

105 CMR 451.200 Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator

Education Director's Office

No Violations Noted

Deputy's Office

No Violations Noted

Break Area in Hall

105 CMR 451.200* Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, gaskets damaged on right side refrigerator

105 CMR 451.200* Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, disposable utensils not kept covered

105 CMR 451.200* Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, excessive ice buildup in freezer

Substance Abuse Office

105 CMR 451.353* Interior Maintenance: Ceiling tiles water damaged

Male Staff Bathroom

105 CMR 451.123* Maintenance: Partitions rusted near urinal

Classroom # 5

No Violations Noted

Teacher's Office

Unable to Inspect --In Use

Classroom # 4

No Violations Noted

Classroom # 3

No Violations Noted

Classroom # 2

No Violations Noted

Social Worker's Office

No Violations Noted

Female Staff Bathroom

No Violations Noted

Slop Sink Room

No Violations Noted

Library

No Violations Noted

Parole Office

No Violations Noted

Receiving*County Lock Up*

105 CMR 451.117*

Toilet Fixtures: Toilet fixtures dirty in cell # 3

Holding Area # 1

105 CMR 451.353*

Interior Maintenance: Floor damaged around floor drain in holding cell # 1

Intake Cages

No Violations Noted

Holding Area # 2

No Violations Noted

Shakedown

No Violations Noted

Property Room

No Violations Noted

Records

No Violations Noted

Record's Bathroom

105 CMR 451.123

Maintenance: Sink faucet rusted

Utility Closet

105 CMR 451.353*

Interior Maintenance: Wet mop stored in bucket

Offices/Medical

105 CMR 451.353*

Interior Maintenance: Floor paint damaged in back offices

ID Room

No Violations Noted

Classification

No Violations Noted

Maintenance Corridor*Staff Bathroom*

105 CMR 451.110(A)

Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink

Inmate Bathroom

No Violations Noted

Staff Bathroom inside Office

No Violations Noted

Laundry Area

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator temperature recorded at 50°F

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator dirty

Tool Crib

No Violations Noted

Electrical Shop

No Violations Noted

Welding Area

105 CMR 451.350*

Structural Maintenance: Exterior door not rodent and weathertight

Tool Cage

No Violations Noted

EHSO Office

No Violations Noted

Modular Administration Building

Lobby

Waiting Area

105 CMR 451.353*

Interior Maintenance: Floor damaged near front door

Male Bathroom

105 CMR 451.123*

Maintenance: Wall tiles missing

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, hot water faucet not working

Female Bathroom

105 CMR 451.123*

Maintenance: Floor tiles damaged

Mail Room

No Violations Noted

Control 3

105 CMR 451.353*

Interior Maintenance: Floor damaged throughout break area

105 CMR 451.353

Interior Maintenance: Floor dirty

Control Bathroom

105 CMR 451.123*

Maintenance: Floor tiles missing and damaged

Special Services Corridor

Female Bathroom

105 CMR 451.123*

Maintenance: Wall tile damaged near toilet

Male Bathroom

105 CMR 451.123*

Maintenance: Faucet fixture corroded

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, faucet at handwash sink leaking

Slop Sink Room

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

D-Board Office

105 CMR 451.353*

Interior Maintenance: Floor damaged at doorway

Dispatch

No Violations Noted

Evidence Closet

Unable to Inspect - Locked

3 Offices

No Violations Noted

Female Locker Room

105 CMR 451.123*

Maintenance: Wall cracked in handicapped shower

105 CMR 451.123*

Maintenance: Floor dirty in handicap shower

Male Locker Room

105 CMR 451.123*

Maintenance: Grab bar rusted in handicap shower

105 CMR 451.123*

Maintenance: Shower curtain dirty in shower # 1

105 CMR 451.123*

Maintenance: Ceiling tiles water damaged

Staff Training Room A & B (Room B Unable to Inspect – In Use)

No Violations Noted

Investigations Office

No Violations Noted

2nd Floor

Personnel Offices

No Violations Noted

Break Room

No Violations Noted

Copy Room

No Violations Noted

Closet with Microwave

No Violations Noted

Deputy's Office/Legal

No Violations Noted

Director of Maintenance Office

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator

North Male Bathroom (near slop sink)

No Violations Noted

Slop Sink Room

105 CMR 451.353*

Interior Maintenance: Floor tiles missing

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, drain cover not secure in slop sink

North Female Bathroom (near slop sink)

No Violations Noted

Assistant Superintendent's Office

Unable to Inspect – Locked

South Male Bathroom

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, hot water faucet not working

South Female Bathroom

No Violations Noted

Internal Affairs

No Violations Noted

Trap

Pedestrian Trap

105 CMR 451.353*

Interior Maintenance: Baseboard missing

Bathroom in Pedestrian Trap

No Violations Noted

Visits Waiting Area

105 CMR 451.353*

Interior Maintenance: Baseboard damaged near trap and door leading to exterior

Modular Gym

Inmate Bathroom # 104

105 CMR 451.123*

Maintenance: Walls dirty near toilet

105 CMR 451.123*

Maintenance: Dead flies in light shield

105 CMR 451.126*

Water Supply: No hot water supplied to handwash sink

105 CMR 451.124*

Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink

Staff Bathroom # 105

105 CMR 451.123*

Maintenance: Wall access panel rusted

105 CMR 451.123*

Maintenance: Shower floor dirty

Sprinkler Room/Mop Closet

No Violations Noted

Storage Room # 108

No Violations Noted

Gym

105 CMR 451.350*

Structural Maintenance: Wall damaged

105 CMR 451.353*

Interior Maintenance: Walls dirty throughout gym

105 CMR 451.141*

Screens: Several screens damaged

105 CMR 451.353

Interior Maintenance: Ceiling light not secured

Control # 102

No Violations Noted

Modular Infirmary

2nd Floor

Inmate Bathroom # 244

105 CMR 451.123*

Maintenance: Wall tiles missing

105 CMR 451.123

Maintenance: Floor tiles damaged

<i>Office # 256</i>	No Violations Noted
<i>Holding Cell</i>	No Violations Noted
<i>Nurse's Station # 233</i> 105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
<i>Room # 234</i>	No Violations Noted
<i>Slop Sink # 245</i>	No Violations Noted
<i>Room # 236</i> 105 CMR 451.110(A)	Hygiene Supplies at Toilet and Handwash Sink: No paper towels at handwash sink
<i>Male Bathroom # 243</i> 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123* 105 CMR 451.123	Maintenance: Floor tiles damaged Maintenance: Ceiling water damaged Maintenance: Floor dirty Maintenance: Wood left unfinished under sink and toilet
<i>X-Ray Room # 242</i>	No Violations Noted
<i>Room # 237</i>	No Violations Noted
<i>Slop Sink Room # 238</i> 105 CMR 451.353	Interior Maintenance: Inadequate ventilation, ceiling vent blocked
<i>Lieutenant's Office # 239</i>	No Violations Noted
<i>Room # 241</i>	No Violations Noted
<i>Mental Health Office # 248</i> 105 CMR 451.353* 105 CMR 451.350	Interior Maintenance: Ceiling tile missing Structural Maintenance: Ceiling leaking
<i>Parole Office # 250</i> 105 CMR 451.141*	Screens: Screens damaged
<i>Dentist Room # 253</i>	Unable to Inspect – In Use
<i>Room # 254</i> 105 CMR 451.353*	Interior Maintenance: Floor tiles missing
<i>Diabetic Office</i>	No Violations Noted

Office # 246

Unable to Inspect -- Area No Longer Used

Female Bathroom # 258

105 CMR 451.123*

Maintenance: Floor tiles damaged

105 CMR 451.126

Hot Water: Hot water temperature recorded at 106⁰F

Nurse's Office # 232

No Violations Noted

Break Room (Medical Records) # 214

No Violations Noted

Room # 230

105 CMR 451.353*

Interior Maintenance: Ceiling paint damaged

Cell # 226-229

Unable to Inspect -- Area No Longer Used

Handicapped Shower

Unable to Inspect -- Area No Longer Used

Captain's Office

Unable to Inspect -- Locked

Optometrist's Office

Unable to Inspect -- In Use

Administrator's Office

No Violations Noted

HIV Office

No Violations Noted

Supply Closet

No Violations Noted

Cell # 206-209

Unable to Inspect -- Area No Longer Used

DOL Unit

Unable to Inspect -- Area No Longer Used

Medical Closet

No Violations Noted

1st Floor

Mod Med Line

Unable to Inspect -- Area No Longer Used

Classrooms

Unable to Inspect -- Area No Longer Used

Hallway between Classrooms

105 CMR 451.353*

Interior Maintenance: Door frame damaged and rusted on door leading to exterior

Roll Call Room (New)

105 CMR 451.353*

105 CMR 451.141*

Interior Maintenance: Floor tiles damaged

Screens: Screens damaged

Classroom Office

Unable to Inspect – Area No Longer Used

Roll Call Room (Old)

Unable to Inspect – Area No Longer Used

Break Area

Unable to Inspect – Area No Longer Used

Bathroom # 108

Unable to Inspect – Area No Longer Used

Slop Sink # 109

Unable to Inspect – Area No Longer Used

Storage Area

Unable to Inspect – Area No Longer Used

Modular Visiting Area

Visiting Sections

Section A

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

Interior Maintenance: Floor tiles missing

Classifications Office

No Violations Noted

Additional Offices

No Violations Noted

Section B

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Floor tiles missing

Interior Maintenance: Wall damaged around door leading to exterior

Section C

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Floor tiles missing in inmate section

Interior Maintenance: Countertop surface damaged throughout section

Social Workers Office

105 CMR 451.353*

105 CMR 451.353*

Interior Maintenance: Floor tiles missing outside of office

Interior Maintenance: Floor dirty

Back Area

Bathroom near Slop Sink

105 CMR 451.123*	Maintenance: Floor dirty
105 CMR 451.123*	Maintenance: Ceiling vent dusty
105 CMR 451.126*	Hot Water: Hot water temperature recorded at 85°F
105 CMR 451.123*	Maintenance: Faucet fixture dirty
105 CMR 451.353*	Interior Maintenance: Floor tiles missing outside bathroom

Slop Sink

105 CMR 451.353*	Interior Maintenance: Floor tiles missing
105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket

Social Worker Interview Area

105 CMR 451.353*	Interior Maintenance: Small holes in floor throughout area
105 CMR 451.353*	Interior Maintenance: Floor tiles damaged

IP Break Room

105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets damaged

Inmate Interview Room

105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
105 CMR 451.353*	Interior Maintenance: Counter tops dirty

Side Door Exit to Yard

105 CMR 451.353*	Interior Maintenance: Floor tiles missing at door
------------------	---

Receiving

Entrance Hallway

105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
------------------	---

Personal Property # 1

105 CMR 451.353*	Interior Maintenance: Floor tiles missing and damaged
105 CMR 451.353*	Interior Maintenance: Hole in ceiling in far back corner
105 CMR 451.353*	Interior Maintenance: Ceiling water damaged
105 CMR 451.353*	Interior Maintenance: Ceiling vent not secured to ceiling

Chemical Room

No Violations Noted

Personal Property # 2

105 CMR 451.353*	Interior Maintenance: Wall paint peeling
------------------	--

Urinalysis Storage

105 CMR 451.353*	Interior Maintenance: Ceiling panel not secured
------------------	---

Urinalysis Office

Unable to Inspect – Locked

Slop Sink Room

No Violations Noted

Inmate Bathroom # 119

105 CMR 451.123*

Maintenance: Wall and wall tiles damaged near toilet

Staff Bathroom # 120

No Violations Noted

Shower # 118

No Violations Noted

Shower # 117

No Violations Noted

Processing Area

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

Waiting Room

105 CMR 451.353*

Interior Maintenance: Floor paint damaged

Break Area

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

105 CMR 451.200

Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, no functioning thermometer in refrigerator

Back Area

Sally Port

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

105 CMR 451.350*

Structural Maintenance: Exterior door not rodent and weathertight

Clothing Room

105 CMR 451.353*

Interior Maintenance: Floor tile damaged

Court Storage

105 CMR 451.353*

Interior Maintenance: Floor tiles missing

105 CMR 451.353*

Interior Maintenance: Light rusted

105 CMR 451.353*

Interior Maintenance: Walls left unfinished

105 CMR 451.350

Structural Maintenance: Ceiling tiles missing

Cells

105 CMR 451.353*

Interior Maintenance: Floor paint peeling in cell # 107

105 CMR 451.353*

Interior Maintenance: Window sill damaged in cell # 104

Back Exit

105 CMR 451.350

Structural Maintenance: Walls damaged

VOC Laundry

1st Floor

Inmate Bathroom

105 CMR 451.123*

Maintenance: Floor paint peeling

Laundry

No Violations Noted

<i>Chemical Storage</i> 105 CMR 451.353	Interior Maintenance: Wet mop stored in bucket
<i>Clothing Storage Room</i>	No Violations Noted
<i>Office</i>	No Violations Noted
<i>Slop Sink Closet</i>	No Violations Noted
<i>Staff Bathroom</i> 105 CMR 451.123*	Maintenance: Floor paint peeling
<i>Classrooms A-D</i>	No Violations Noted
<i>IT Break Area</i> 105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
<i>Hallway</i>	No Violations Noted
2nd Floor	
<i>Room # 203</i> 105 CMR 451.353* 105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged Interior Maintenance: Wall vent missing grille/louver
<i>Room # 210</i>	No Violations Noted
<i>Room # 202</i> 105 CMR 451.360* 105 CMR 451.350	Protective Measures: Bird droppings observed on floor Structural Maintenance: Wall louver removed, not weathertight
<u>II Building</u>	
105 CMR 451.320* 105 CMR 451.343*	Cell Size: Inadequate floor space in all cells Electric Fixtures in Cell: No electrical outlet in all cells
<i>Control Booth</i> 105 CMR 451.350	Structural Maintenance: Ceiling tiles damaged
<i>Control Bathroom</i> 105 CMR 451.123* 105 CMR 451.126	Maintenance: Floor tiles missing in bathroom Hot Water: Hot water temperature recorded at 100°F

Cells

105 CMR 451.350*	Structural Maintenance: Unable to open or close window in cell # 109, 110, 112, 115, 120, and 126
105 CMR 451.350	Structural Maintenance: Unable to open or close window in cell # 108
105 CMR 451.350*	Structural Maintenance: Window leaking in cell # 113
105 CMR 451.353*	Interior Maintenance: Wall paint peeling in cell # 102, 114, 117, and 131
105 CMR 451.353	Interior Maintenance: Wall paint peeling in cell # 124
105 CMR 451.353*	Interior Maintenance: Ceiling paint damaged in cell # 131
105 CMR 451.344*	Illumination in Habitable Areas: Lights not functioning properly, light out over sink in cell # 135
105 CMR 451.344*	Illumination in Habitable Areas: Lights not functioning properly, light out in cell # 157

Day Room

No Violations Noted

Chemical Room

No Violations Noted

Interview Room

No Violations Noted

Showers

No Violations Noted

I Building

Control Booth

105 CMR 451.350	Structural Maintenance: Ceiling tiles damaged
-----------------	---

Control Bathroom

105 CMR 451.383(B)*	Fire Safety System: Facility not in compliance with 780 CMR Massachusetts Building Code provisions for fire safety, paper towels stored within 18" of the ceiling in the bathroom
105 CMR 451.123*	Maintenance: Floor paint damaged

Cells

105 CMR 451.350*	Structural Maintenance: Unable to open and close window in cell # 176 and 178
105 CMR 451.350	Structural Maintenance: Unable to open and close window in cell # 194
105 CMR 451.353*	Interior Maintenance: Wall paint peeling in cell # 184
105 CMR 451.353*	Interior Maintenance: Bed paint damaged in cell # 178
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, toilet not flushing properly in cell # 194

Interview Room

Unable to Inspect — Locked

Slop Sink

105 CMR 451.353*	Interior Maintenance: Floor paint peeling
------------------	---

Day Room

No Violations Noted

Showers

105 CMR 451.123*	Maintenance: Soap scum on walls in shower # 2 and 8
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 6
105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # 3

J Building

Cells

105 CMR 451.350*	Structural Maintenance: Unable to open or close window in cell # 240
105 CMR 451.350	Structural Maintenance: Unable to open or close window in cell # 241
105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 257 and 272
105 CMR 451.140*	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 268
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 260 and 263

Day Room

No Violations Noted

Slop Sink Room

No Violations Noted

Interview Room

No Violations Noted

Showers

105 CMR 451.123*	Maintenance: Column outside shower damaged at shower # 3 and 7
105 CMR 451.123	Maintenance: Soap scum on walls in shower # 1, 4, 5, and 6

K Building

105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
105 CMR 451.343*	Electric Fixtures in Cell: No electrical outlet in all cells

Control Booth

105 CMR 451.350	Structural Maintenance: Ceiling tiles missing
-----------------	---

Control Bathroom

No Violations Noted

Day Room

No Violations Noted

Cells

105 CMR 451.350*	Structural Maintenance: Unable to open or close window in cell # 303
105 CMR 451.353*	Interior Maintenance: Uncovered junction box in cell # 284, 299, 305, 311, and 314
105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 294, 295, 333, 338, and 340
105 CMR 451.140	Adequate Ventilation: Inadequate ventilation, wall vent blocked in cell # 318
105 CMR 451.350	Structural Maintenance: Leak outside cell # 283 into light fixture

Showers

105 CMR 451.123	Maintenance: Floor dirty in shower # 3
105 CMR 451.123	Maintenance: Column outside shower rusted at shower # 4 and 7

Chemical Room

105 CMR 451.353*	Interior Maintenance: Wall paint damaged around slop sink
------------------	---

Interview Room

No Violations Noted

L Building

105 CMR 451.320*	Cell Size: Inadequate floor space in all cells
105 CMR 451.343*	Electric Fixtures in Cell: No electrical outlet in all cells

Day Room

105 CMR 451.353

Interior Maintenance: Wall paint damaged by phones

Cells

105 CMR 451.350*

Structural Maintenance: Unable to open or close window in cell # 357, 360, and 385

105 CMR 451.350

Structural Maintenance: Unable to open or close window in cell # 354

105 CMR 451.353*

Interior Maintenance: Wall paint damaged in cell # 353, 362, 364, 367, 383, 388, and 390

105 CMR 451.353

Interior Maintenance: Ceiling paint damaged in cell # 394

Showers

105 CMR 451.123*

Maintenance: Soap scum on walls in shower # 4, 5, and 6

105 CMR 451.123

Maintenance: Soap scum on walls in shower # 3

105 CMR 451.123

Maintenance: Walls dirty in shower # 4, 5, and 6

105 CMR 451.123

Maintenance: Floor dirty in shower # 5

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, shower # 6 leaking

Chemical Room

No Violations Noted

Interview Room

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, hot water faucet not working

105 CMR 451.130

Plumbing: Plumbing not maintained in good repair, sink drain cover missing

Work Release

Control Booth

No Violations Noted

Strip Search Room

105 CMR 451.353*

Interior Maintenance: Ceiling tiles water damaged

105 CMR 451.353*

Interior Maintenance: Floor tiles damaged

Chemical Closet

105 CMR 451.353*

Interior Maintenance: Ceiling tiles water damaged

Office

No Violations Noted

Cells

105 CMR 451.353*

Interior Maintenance: Ceiling damaged in cell # 5

105 CMR 451.353*

Interior Maintenance: Ceiling paint peeling near window in cell # 11

105 CMR 451.353*

Interior Maintenance: Ceiling paint peeling in cell # 6

105 CMR 451.350*

Structural Maintenance: Window pane broken in cell # 7

105 CMR 451.353

Interior Maintenance: Light shield missing in cell # 4

Slop Sink Room (left)

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, faucet leaking

105 CMR 451.130*

Plumbing: Plumbing not maintained in good repair, drain cover missing

Showers (left)

105 CMR 451.123*

Maintenance: Ceiling louver/grille missing

105 CMR 451.123*

Maintenance: Mold observed on ceiling tiles

105 CMR 451.123*

Maintenance: Floor tiles missing in shower # 3

105 CMR 451.123

Maintenance: Floor tiles missing in shower # 5

105 CMR 451.123*

Maintenance: Wall tiles damaged in shower # 5

Inmate Bathroom (left)

105 CMR 451.123*	Maintenance: Partitions damaged in stall # 2 and 3
105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, faucet loose at handwash sink # 1
105 CMR 451.123	Maintenance: Unfinished wood on wall

Chow Hall and Storage Rooms

105 CMR 451.353*	Interior Maintenance: Seats damaged at dining tables
105 CMR 451.353*	Interior Maintenance: Wall damaged near door
105 CMR 451.200	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, food warmer gaskets damaged

Old Kitchen Area

No Violations Noted

Day Room

No Violations Noted

Storage Room

No Violations Noted

Laundry

105 CMR 451.353*	Interior Maintenance: Floor tiles damaged
------------------	---

Showers (right)

105 CMR 451.123*	Maintenance: Mold on ceiling
105 CMR 451.123*	Maintenance: Ceiling tile damaged over shower # 1
105 CMR 451.123*	Maintenance: Wall tiles damaged in shower # 1
105 CMR 451.123	Maintenance: Caulking missing between wall tiles in shower # 2
105 CMR 451.123*	Maintenance: Floor damaged in shower # 2 and 3
105 CMR 451.123	Maintenance: Floor damaged in shower # 4

Staff Bathroom

105 CMR 451.123	Maintenance: Ceiling paint damaged
-----------------	------------------------------------

Inmate Bathroom (right)

Unable to Inspect –In Use

Tower

1st Floor

105 CMR 451.353*	Interior Maintenance: Floor dirty
------------------	-----------------------------------

2nd Floor

105 CMR 451.350*	Structural Maintenance: Wall damaged
105 CMR 451.350*	Structural Maintenance: Ceiling damaged
105 CMR 451.353*	Interior Maintenance: Wall paint peeling
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, light out
105 CMR 451.126*	Hot Water: Hot water temperature recorded at 99 ⁰ F at handwash sink
105 CMR 451.123	Maintenance: Handwash sink dirty
105 CMR 451.123	Maintenance: Toilet dirty
105 CMR 451.123	Maintenance: Floor dirty

3rd Floor

105 CMR 451.350*	Structural Maintenance: Wall damaged
105 CMR 451.353*	Interior Maintenance: Wall board missing
105 CMR 451.344*	Illumination in Habitable Areas: Light not functioning properly, missing light bulbs in light fixture
105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, excessive ice buildup in freezer

Warehouse Building (outside)

Staff Gym

Weight Area

105 CMR 451.353*	Interior Maintenance: Dead insects observed in light shield
------------------	---

Female Bathroom

105 CMR 451.123*	Maintenance: Wall water damaged near toilet
105 CMR 451.123	Maintenance: Dead insects observed in light shield

Male Bathroom

105 CMR 451.123*	Maintenance: Column damaged outside shower
105 CMR 451.123*	Maintenance: Mold observed on bench seat in shower
105 CMR 451.123*	Maintenance: Wall water damaged near toilet
105 CMR 451.123	Maintenance: Dead insects observed in light shield
105 CMR 451.123	Maintenance: Ceiling light out

Chemical Room

No Violations Noted

Office

No Violations Noted

Warehouse

Office

No Violations Noted

Break Area

No Violations Noted

Inmate Bathroom

No Violations Noted

Staff Bathroom

No Violations Noted

Chemical Room

No Violations Noted

Walk-In Freezer

No Violations Noted

Dry Storage Closet

No Violations Noted

Exterior Cooler # 1
No Violations Noted

Exterior Cooler # 2
No Violations Noted

Garage

Transportation Office
No Violations Noted

Kitchen Area
No Violations Noted

Bathroom
No Violations Noted

Staff Bathroom
Unable to Inspect - In Use

Tool Room
No Violations Noted

Wash Room
No Violations Noted

Garage Room
No Violations Noted

Key Control
No Violations Noted

Annex
105 CMR 451.322* Cell Size: Inadequate floor space

Control Booth
No Violations Noted

Control Bathroom
No Violations Noted

Visiting Area (outside)
No Violations Noted

Female Staff Bathroom
No Violations Noted

Staff Locker Room
No Violations Noted

Male Staff Bathroom/Storage
No Violations Noted

Visiting Area (inside)
105 CMR 451.130* Plumbing: Plumbing not maintained in good repair, bubbler out-of-order

<i>Food Service Area</i>	No Violations Noted
<i>Dining Area</i>	Unable to Inspect - In Use
<i>Social Worker's Office</i>	Unable to Inspect - In Use
<i>Showers</i>	Unable to Inspect --- In Use
<i>Storage/Boiler Room</i>	Unable to Inspect -- In Use
<i>Medical</i>	Unable to Inspect – In Use
<i>Chemical Closet with Books</i>	No Violations Noted
<i>Toilets</i>	
105 CMR 451.124*	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink/toilet unit # 1 and 8
105 CMR 451.124	Water Supply: Insufficient cold water supply in quantity and pressure at handwash sink/toilet unit # 5
105 CMR 451.124	Water Supply: Insufficient hot water supply in quantity and pressure at handwash sink/toilet unit # 11
105 CMR 451.124*	Water Supply: Insufficient water supply in quantity and pressure at handicap handwash sink/toilet unit
<i>Sink Area</i>	
105 CMR 451.124*	Water Supply: Insufficient water supply in quantity and pressure at handwash sink # L2
105 CMR 451.126*	Water Supply: No cold water supplied to middle handwash sink
105 CMR 451.126*	Water Supply: No cold water supplied to handwash sink # L3
<i>Sleeping Area</i>	
105 CMR 451.101	Blankets: Blanket damaged in at bed # 55
<i>Meeting Room # 1</i>	No Violations Noted
<i>Laundry</i>	No Violations Noted

Observations and Recommendations

1. The inmate population was 1083 at the time of inspection.
2. The Department recommends that all showers be identified with a numbering system. This will assist the Department and correctional employees to better identify where issues exist.
3. There were areas of the Modular Infirmary Building that were no longer used and certain areas had restricted access. Inmates have been re-located to the Health Services Infirmary Ward Bunk Room. The Department requests to be kept apprised of any additional changes to the usage of this building.
4. The Department recommends removing the Biohazard sticker on a refrigerator used strictly for food products in the Administrator's Offices on the 2nd floor of the Modular Infirmary building.

This facility does not comply with the Department's Regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice, indicating the specific corrective steps to be taken, a timetable for such steps, and the date by which correction will be achieved. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" (available in both PDF and RTF formats).

To review the Food Establishment regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "Retail" click "105 CMR 590.000 - State Sanitary Code Chapter X - Minimum Sanitation Standards for Food Establishments" and "1999 Food Code".

To review the Labeling regulations please visit the Food Protection website at www.mass.gov/dph/fpp and click on "Food Protection Regulations". Then under "General Food Regulations" click "105 CMR 520.000: Labeling."

This inspection report is signed and certified under the pains and penalties of perjury.

Sincerely,



Amy Medeiros, MPH
Environmental Health Inspector, CSP, BEH

cc: Jana Ferguson, Director, BEH
Steven Hughes, Director, CSP, BEH
Marylou Sudders, Secretary, Executive Office of Health and Human Services
Thomas Turco, Commissioner, DOC
Patrick Ryan, EHSO
Danielle Gagnon, Administrator/Health Inspector, West Boylston Board of Health
Clerk, Massachusetts House of Representatives
Clerk, Massachusetts Senate
Daniel Bennett, Secretary, EOPSS
Nelson Alves, Director, Policy Development and Compliance Unit